

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002525085
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	858150
7. Lease Name or Unit Agreement Name	WEST VACUUM UNIT
8. Well No.	51
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

**SUNDRY NOTICES AND REPORTS ON WELL**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC
3. Address of Operator 205 E. Bender, HOBBS, NM 88240	4. Well Location Unit Letter _____ : _____ 1360 Feet From The SOUTH Line and 150 Feet From The EAST Line Section 33 Township 17S Range 34E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	


11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Notify OCD 24 hours prior to commencing work.
- 2) Move in and rig up pulling unit.
- 3) TOH with production equipment, tubing, cable and pump.
- 4) TIH with 2 7/8" workstring, 5 1/2" CIBP. Set the plug +/- 4400'.
- 5) Spot 30' of cement above the CIBP.
- 6) TIH with 2 7/8" workstring and 5 1/2" Pkr.
- 7) Check casing's integrity. Circulate hole with inhibited fluid and chart as per NMOCD guidelines, 500# for 30 min.
- 8) Request temporary abandoned to 9/1/2003.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Prod. Engineer DATE Sep 14, 98  
TYPE OR PRINT NAME M. Siamak Safargar Telephone No. 397-0429

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY CHRIS WILLIAMS DATE OCT 30 1998  
CONDITIONS OF APPROVAL, IF ANY:

