

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25734	
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B - 1861
7. Lease Name or Unit Agreement Name CENTRAL VACUUM UNIT	
8. Well No.	94
9. Pool Name or Wildcat VACUUM GRAYBURG SAN ANDRES	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WATER INJECTION WELL <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location Unit Letter <u>O</u> : <u>50</u> Feet From The <u>SOUTH</u> Line and <u>2549</u> Feet From The <u>EAST</u> Line Section <u>31</u> Township <u>17S</u> Range <u>35E</u> NMPM <u>LEA</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3979' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ PERF & ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-20-00: MIRU. FLOW BACK & KILL WELL. NDWH. NUBOP.
11-21-00: REL PKR. RESET PKR. PSI CSG TO 500-OK.
11-22-00: REL PKR. CIRC 400 BBLs BRINE. UNABLE TO PULL, RESET PKR.
11-27-00: REL ON/OFF TOOL. KILL WELL W/80 BBLs 13# MUD. LATCH & REL PKR. TIH W/BIT TO 4126'.
11-28-00: TIH & TAG @ 4420'. DISPL MUD W/10# BRINE. C/O 4420-4738. KILL W/13# MUD. PULL BIT TO 4126'.
11-29-00: KILL W/60N BBLs 14.5# MUD. RU LUBRICATOR. TEST TO 1500 PSI-OK. TIH W/PERF GUN. TAG @ 4300'.
11-30-00: KILL WELL. TIH W/MILL, TBG, STRING MILL. TAG @ 4267'. MILL TO 4373'. MILL STUCK. WORK STUCK MILL.
12-01-00: WORK STUCK TBG. TIH W/CHEM CUTTER TO 4239'. ATTEMPT TO CUT TBG. FAILED.
12-04-00: TIH W/CHEM CUTTER. CUT TBG @ 4239'. TIH W/OVERSHOT, BMPR SUB, JARS, DC'S, ACC SUB TO 210'. WELL KICKED.
12-05-00: FLOW WELL DN. KILL W/50 BBLs 14.5# MUD. LATCH ONTO STUCK TBG @ 4228'. JAR ON STUCK TBG. JAR OFF. TIH W/KILL STRING TO 4160'.
12-07-00: TIH W/OVERSHOT, BS, JARS, DC'S, ACC SUB, WS TO 4228'. LATCH ONTO FSH @ 4228'. JAR ON FSH.
12-08-00: REL OVERSHOT. TIH W/INJ TBG. TIH W/OVERSHOT, BS, JARS, DC'S & WS TO 4194'. RD PU. RU PU.
12-11-00: LATCH ONTO FSH @ 4129'. JAR ON STUCK TBG. MOVE UP HOLE @ 5'.
12-12-00: JAR ON STUCK TBG. JAR OFF FSH. TIH W/SLIM HOLE, & WS TO 3977'.
12-14-00: RAN FREE PT. TAG @ 4313'. RAN SPUD BARS, SPUD @ 4313'. RAN STRING SHOT. BACK OFF @ 4279'. TIH W/TBG SCREW IN SUB
12-15-00: SCREW INTO FSH @ 4279'. JAR ON STUCK TBG.
12-18-00: WS PARTED @ 3003'. TIH W/OVERSHOT & WS TO 2916'.
12-19-00: LATCH ONTO FSH @ 3003'. RAN STRING SHOT BACK OFF SCREW IN SUB @ 4279'. PU WS TO 2208'.
12-20-00: TAG FSH @ 4286'. TIH W/OVERSHOT TO 4110'.
12-21-00: TIH TO 4286'. DISPL W/10# BRINE. PULL TO 4106'. TIH W/IB, & TAG @ 4286'. KILL STRING TO 3906'. RECOMMEND P&A.
12-28-00: TIH W/CMT RET ON WS. SET RET @ 4245'. NDBOP. NU TREE. RIG DOWN. WAITING ON P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 1/9/01
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____ DATE JAN 22 2001