Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO. 30-025-26401

DISTRICT II	Comto La Mais	Santa Fe, New Mexico 87504-2088		30-023-20401
P.O. Drawer DD, Artesia, NM 8821	10 Santa Fe, New			5. Indicate Type of Lease STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87	7410			6. State Oil & Gas Lease No. B-1608
CHAINDY	NOTICES AND REPORTS	ON WEI	IS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF DIFFERENT RESERVOIR. USE "APPLICATION FOR PERIOR (FORM C-101) FOR SUCH PROPOSALS.)			OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well:	TIME OF IVITY FOR SUCH PHOPOS	<u></u>		East Vacuum Gb/SA Unit
OIL GAS WELL WELL	ı OTHER	Water	Injection	Tract 3332
2. Name of Operator	- OTHER		411J EC 6 1 UII	8. Well No.
Phillips Petro	leum Company			8. Well No. 001
3. Address of Operator	ream company			9. Pool name or Wildcat
•	Street, Odessa, TX 7	79762	•	Vacuum Gb/SA
4. Well Location				
Unit LetterA:_	1310 Feet From The Eas	st	Line and 20	OO Feet From The North Line
Section 33	Township 17-S			NMPM Lea County
	10. Elevation (Sh	ow whether l	DF, RKB, RT, GR, etc.)	
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	//////////////////////////////////////			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDO		REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	GOPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING			CASING TEST AND CEMENT JOB	
			1	
OTHER:			ОТНЕЯ : Perforat	tions/Stimulation X
	Operations (Clearly state all pertine	nt details, an		tions/Stimulation X ding estimated date of starting any proposed
12. Describe Proposed or Completed work) SEE RULE 1103.	•	nt details, an		
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi	J. NU BOP.	rom 466	d give perlinent dates, includes 81 to surf.	ding estimated date of starting any proposed
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat	J. NU BOP. ng inspection log file ce w/23 gram charges	rom 4668 w/2 SPI	d give perlinent dates, included to surf. F as follows: 4	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots:
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2	J. NU BOP. Ing inspection log file w/23 gram charges 23 shots: 4429'-4432	rom 4668 w/2 SPI	d give pertinent dates, includes 8' to surf. F as follows: 47 shots; 4419'-4	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416'
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots: 4408'-	J. NU BOP. Ing inspection log fine w/23 gram charges Place 3 shots: 4429'-4432' Place 4410', 2', 5 shots.	rom 4668 w/2 SPI ', 3', i	8' to surf. F as follows: 47 shots; 4419'-4	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416'; #, held OK. Swab 4 hrs.
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg	J. NU BOP. Ing inspection log fine w/23 gram charges Place 3 shots: 4429'-4432' Place 4410', 2', 5 shots.	rom 4668 w/2 SPI ', 3', i	8' to surf. F as follows: 47 shots; 4419'-4	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416'
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg ISIP Vac.	J. NU BOP. Ing inspection log fine w/23 gram charges Place 3 shots: 4429'-4432' Place 4410', 2', 5 shots.	rom 4668 w/2 SPI ', 3', i	8' to surf. F as follows: 47 shots; 4419'-4	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416'; #, held OK. Swab 4 hrs.
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg ISIP Vac. 1-2-91: Swab.	J. NU BOP. Ing inspection log fine w/23 gram charges Place 3 shots: 4429'-4432' Place 4410', 2', 5 shots.	rom 4668 w/2 SPI ', 3', i	8' to surf. F as follows: 47 shots; 4419'-4	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416'; #, held OK. Swab 4 hrs.
12-Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg ISIP Vac. 1-2-91: Swab. 1-3-91: ND BOP.	J. NU BOP. Ing inspection log from the second secon	rom 4668 w/2 SPI ', 3', 1 Test I 15% NE	8' to surf. F as follows: 47 shots; 4419'-4 backside to 500#	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416', #, held OK. Swab 4 hrs. 500# salt. Avg press 0#,
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg ISIP Vac. 1-2-91: Swab. 1-3-91: ND BOP. 1-4-91: Press up c	J. NU BOP. Ing inspection log fine w/23 gram charges Place 3 shots: 4429'-4432' Place 4410', 2', 5 shots.	rom 4668 w/2 SPI ', 3', 1 Test I 15% NE	8' to surf. F as follows: 47 shots; 4419'-4 backside to 500#	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416', #, held OK. Swab 4 hrs. 500# salt. Avg press 0#,
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg ISIP Vac. 1-2-91: Swab. 1-3-91: ND BOP. 1-4-91: Press up c for injection.	J. NU BOP. Ing inspection log for the w/23 gram charges and shots: 4429'-4432'-4410', 2', 5 shots. Jer. Pump 5000 gals as a seg/tbg annulus to 50	rom 4668 w/2 SPI ', 3', 1 Test I 15% NE	8' to surf. F as follows: 47 shots; 4419'-4 backside to 500#	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416'; #, held OK. Swab 4 hrs. 500# salt. Avg press 0#,
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg ISIP Vac. 1-2-91: Swab. 1-3-91: ND BOP. 1-4-91: Press up c for injection. 1-5-91: Temp. drop	J. NU BOP. Ing inspection log for the w/23 gram charges and shots: 4429'-4432' 4410', 2', 5 shots. Ger. Pump 5000 gals and seg/tbg annulus to 500.	rom 4668 w/2 SPI ', 3', i Test I 15% NEI	8' to surf. F as follows: 47 shots; 4419'-4 backside to 500#	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416', #, held OK. Swab 4 hrs. 500# salt. Avg press 0#,
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg ISIP Vac. 1-2-91: Swab. 1-3-91: ND BOP. 1-4-91: Press up c for injection. 1-5-91: Temp. drop	J. NU BOP. Ing inspection log for the w/23 gram charges and shots: 4429'-4432'-4410', 2', 5 shots. Jer. Pump 5000 gals as a seg/tbg annulus to 50	rom 4668 w/2 SPI ', 3', i Test I 15% NEI	8' to surf. F as follows: 47 shots; 4419'-4 backside to 500#	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416', #, held OK. Swab 4 hrs. 500# salt. Avg press 0#,
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg ISIP Vac. 1-2-91: Swab. 1-3-91: ND BOP. 1-4-91: Press up c for injection. 1-5-91: Temp. drop 2-18-91: Injecting	J. NU BOP. Ing inspection log for the w/23 gram charges as shots: 4429'-4432' 4410', 2', 5 shots. Iger. Pump 5000 gals as a sight of the control of the cont	rom 4668 w/2 SPI ', 3', 1 Test I 15% NE	d give pertinent dates, included 8' to surf. F as follows: 47 shots; 4419'-4backside to 500# Fe HCL - drop 55	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416'; #, held OK. Swab 4 hrs. 500# salt. Avg press 0#,
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'-12-31-90: RU Charg ISIP Vac. 1-2-91: Swab. 1-3-91: ND BOP. 1-4-91: Press up c for injection. 1-5-91: Temp. drop 2-18-91: Injecting Job complete.	J. NU BOP. Ing inspection log for the w/23 gram charges as shots: 4429'-4432' 4410', 2', 5 shots. Iger. Pump 5000 gals as a sight of the control of the cont	rom 4668 w/2 SPI ', 3', Test I 15% NEI	d give pertinent dates, included 8' to surf. F as follows: 47 shots; 4419'-4backside to 500# Fe HCL - drop 55	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416', #, held OK. Swab 4 hrs. 500# salt. Avg press O#, CD test. Test OK. Hook up
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'- 12-31-90: RU Charg ISIP Vac. 1-2-91: Swab. 1-3-91: ND BOP. 1-4-91: Press up c for injection. 1-5-91: Temp. drop 2-18-91: Injecting Job complete. I hereby certify that the information above	ng inspection log free w/23 gram charges 3 shots: 4429'-4432'4410', 2', 5 shots. Ger. Pump 5000 gals csg/tbg annulus to 500.	rom 4668 w/2 SPI ', 3', Test I 15% NEI	d give pertinent dates, included 8' to surf. F as follows: 47 shots; 4419'-4 backside to 500# Fe HCL - drop 55	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416', #, held OK. Swab 4 hrs. 500# salt. Avg press O#, CD test. Test OK. Hook up
12. Describe Proposed or Completed work) SEE RULE 1103. 12-27-90: MIRU DDU 12-28-90: Run casi 12-30-90: Perforat 4433'-4444', 11', 2 3', 7 shots; 4408'- 12-31-90: RU Charg ISIP Vac. 1-2-91: Swab. 1-3-91: ND BOP. 1-4-91: Press up c for injection. 1-5-91: Temp. drop 2-18-91: Injecting Job complete. I hereby certify that the information above	ng inspection log free w/23 gram charges 3 shots: 4429'-4432' 4410', 2', 5 shots. Ger. Pump 5000 gals csg/tbg annulus to 500.	rom 4668 w/2 SPI ', 3', Test I 15% NEI	d give pertinent dates, included 8' to surf. F as follows: 47 shots; 4419'-4 backside to 500# Fe HCL - drop 55	ding estimated date of starting any proposed 4496'-4505', 9', 19 shots: 4422', 3', 7 shots: 4413'-4416', #, held OK. Swab 4 hrs. 500# salt. Avg press 0#, CD test. Test OK. Hook up

APPROVED BY