STATE OF NEW MEXICO MERGY AND MINERALS DEPARTMENT

wo, er turits streives	1
OISTHUBULION	
BANTA FE	
814E	
U.S.G.S.	
LAND OFFICE	
OHEGAT ()	1 1

OISTRUBE	JEION	}	P. O. BOX	C 2088			Form C-103 Revised 10	
BANTAFE		SANT	A FE, NEW	MEXICO 87501			K641260 13	
PILE					[Sa	Indicate Type	of Leaso	
U.S.G.S.						State X	Foo	
LAND OFFIC	E .	1				·		
ROTARSHO		1			5.	State Off & Go	is Lease No.	
L		API No.	. 30-025-2	6578	1	B-1501		
	SUMDR	RY NOTICES AND RI	EDODIS ON	WELLS			1111111	
(00 HOT US)	E THIS FORM FOR PRO	ዕቦዕሄሐኒቴ ተጋ ሮብ1ኒኒ ዕጽ የፅ ወደ	EEPEN OR PLUG BA	ICA TO A DIFFERENT RESERVO	in.			
	USE APPLICATI	TION FOR PERMIT -" (FORM	C-1017 FOR 30CF	TRUPOJACS.	7.	Upit Agreemen	at Name	
014 (7) 643						7. Unit Agreement Name East Vacuum		
west L	well []	othen. Water:	injection			Gb/SA		
iame of Operator					0.	East Vac	uum Gb/SA	
nillips Pe	troleum Compa	any					act 2923	
ddress of Opera	itor				9.	Well No.		
om 401. 4	001 Penbrook	Street, Odessa	Texas 7	9762		002		
ocation of Well					10	, Field and Pa	ool, or Wildcat	
		1330	weet	60		Vacuum G	1./CA	
UNIT LETTER		TOOM TH	£ West	LINE AND60	- FEET FROM	7777777	mmm	
THE	th LINE. SECTIO	10H 29 TOWN	17-S	35-E	NMPM. N	///////		
_						<i>1111111</i>	777777	
1111111		15, Elevation	. (Show whether l	DF, RT, GR, etc.)	12	. County		
HHHH	(1/////////////////////////////////////	3975'	GR 398	1.2' RKB	-	Lea		
TITITITI .	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	7-7-7-7-7-7-1			oet or Other			
			o indicate is	ature of Notice, Rep				
	NOTICE OF IN	NTENTION TO:		SUE	SEQUENT R	EPORT OF		
RFORM REMEDIAL	. WOAR	PLUG AN	D ABANDON	REMEDIAL WORK		ALTE	RING CASING	
MASA YILBAROSM				COMMENCE DRILLING OPNS.		PLUG	AND ABAHDONME	
	7=4	CHANGE	PLANS [7]	CASING TEST AND CEMENT .	ıoa 🗂			
LL OR ALTER CAS	1NG			отнея Equip a		e water		
				injection pe				
OTHER				injection pe	l Older in	A NO. 04		
	and an Completed O	parations (Clearly state)	Il pertinent deta	ils, and give pertinent date	es including est	imated date of	starting any pr	
work) SEE RUI	LE 1103.	perditions (Cicari) state	ni perineni dela	ins, and give person and	.,		, ,	
			• .					
Per Order	PMX 84							
		s and 2-3/8" tbg	. Set 147	' jts 2-3/8" plas	tic-lined	tbg w/Bal	er Lok-	
11/14/80	Pulled rods							
11/14/80								
		on-off tool at 4						
11/15								
	Set pkr w/o		496'.					
11/15 12/2/80	Set pkr w/o	on-off tool at 4	496'. line.	000 111		,	1 , ,	
11/15	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l	.000 bbls per day	at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l	.000 bbls per day in prior to conv	at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80	Set pkr w/o Connected w Started wat	on-off tool at 4 water injection ter injection at	496'. line. rate of l		at zero p			
11/15 12/2/80 12/3/80	Set pkr w/o Connected w Started wat casing perf	on-off tool at 4 vater injection at 1 to 1	496'. line. rate of l Well shut	in prior to conv	at zero p ersion to			
11/15 12/2/80 12/3/80	Set pkr w/o Connected w Started wat casing perf	on-off tool at 4 vater injection at 1 to 1	496'. line. rate of l Well shut		at zero p ersion to			
11/15 12/2/80 12/3/80	Set pkr w/o Connected w Started wat casing perf	vater injection at the injection at the state of the stat	line. rate of 1 Well shut	in prior to conv	at zero p ersion to	water inj	ection.	
11/15 12/2/80 12/3/80	Set pkr w/o Connected w Started wat casing perf	on-off tool at 4 vater injection at 1 to 1	line. rate of 1 Well shut	in prior to conv	at zero p ersion to	water inj	ection.	
11/15 12/2/80 12/3/80	Set pkr w/o Connected w Started wat casing perf	vater injection at the injection at the state of the stat	line. rate of 1 Well shut	in prior to conv	at zero p ersion to	water inj	ection.	
11/15 12/2/80 12/3/80	Set pkr w/o Connected w Started wat casing perf	vater injection at the injection at the state of the stat	line. rate of 1 Well shut	in prior to conv	at zero p ersion to	water inj	ection.	
11/15 12/2/80 12/3/80	Set pkr w/o Connected w Started wat casing perf	vater injection at the injection at the state of the stat	line. rate of 1 Well shut	in prior to conv	at zero p ersion to	water inj	ection.	