STATE OF NEW MEXICO

THREE WIS INTERESTORIES OF	_1 >(11)131621
na. ar cortes accesses	
DISTRIBUTION	
SAHTA PE	
716%	
U.S.C.S.	
LAND OFFICE	
Deraston	1 1 1

JIL CONSERVATION DIVISION

10. 40 (00)		FORM C-103
ROHTURISTEIG	P. O. BOX 2088	Revised 10-1-78
SANTAFE	SANTA FE, NEW MEXICO 37501	
711.8		5a. Indicata Type of Lease
U.S.C.S.		State X Fee .
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		
Carrier and a fine include a section of the section		- The state of the
the first and the second of th	DEPORTS OF MET 1 C	
SUNDRY N	NOTICES AND REPORTS ON WELLS	voix. ([[[]]]]]]]]]]
USE "APPLICATION P	OTICES AND REPORTS ON MELLO. LES TO DATEL OR TO ELPEN OR PEUC FACE TO A DIFFERENT RESERON PERMIT - " (FORM C-1011 FOR SUCH PROPOSALS.)	7. Unit Agreement Name
The state of the s		
OIL GAS	Old Well Drilling Deeper	
With Last With the world with the wo	OTHER.	8. Farm or Lease Name
Name of Operator		New Mexico State
Knox Industries, In	nc.	9. Well No.
Address of Operator		2
	and Ty 79702	
PO Box 3023 Midla	and ix 17702	10. Field and Pool, or Wildcat
Location of Well		Scharb Morrow
н 198	80 FEET FROM THE NORTH LINE AND 660	FEET FROM THE THE TOTAL THE TANK THE THE TANK TH
	1 TOWNSHIP 198 RANGE 34E	Marie (1) Milliman
YHY LINE, SECTION _	TOWNSHIP RANGE	
		12, County
	15. Elevation (Show whether DF, RT, GR, etc.)	
	3989 GR	Lea
<u> </u>	in a thing Name of Marine R	aport of Other Data
6. Check App	propriate Box To Indicate Nature of Notice, R	UBSEQUENT REPORT OF:
NOTICE OF INT	ENTION TO:	DB2EQUEAT RCLOKE OF
		·
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE ORILLING OF	THE X PLUG AND ABANDONMENT
TEMPORARILY ABANDON		
PULL OF ALTER CASING	CHANGE PLANS CASING TEST AND CEME	l l
PULL ON ACTON CONTRACTOR CONTRACTOR	OTHER	
OTHER		
	Charly state all pertinent details, and give pertinent	lates, including estimated date of starting any propose
17. Describe Proposed or Completed Opera	ations (Clearly state all pertinent details, and give pertinent	•
work) SEE RULE 1103.		

Began to MI & RURT on Feb. 25, 1981. On Feb. 28, Yellowjacketed BOPs, but would not hold pressure. Repaired BOPs and re-tested, checked out OK, 5000 psi for 30 minutes. Started picking up drill collars and started in hole. FIH to cement retainer at 9000'. Drilled out retainer and cement and RIH to 10,030'. Drilled out retainer and cement at 10,030, and RIH to float collar. Drilled out float collar, shoe joint, and shoe. On March 2, 1981, began drilling out from under $5\frac{1}{2}$ " casing at 10,950'. Pressured up on shoe with 1500 psi for 30 minutes, OK. Now drilling ahead with 10# brine for circulating fluid in 4 3/4" hole.

hereby certify that	the information above is true and co	omplete to the best of my knowledge and belief.		
at 1		Production Manager	DATE	3/9/81
				&
		TITLE	DATE	