State of New Mexico nerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

OIL	CONSERVATION DIVISION
	P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28079

5.	Indicate	Туре	of	Lease	,
				STATE	Ì

DISTRICT III	STATE FEE XX		
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name		
1. Type of Well: OIL GAS WELL XX WELL OTHER	Ora Jackson		
2. Name of Operator	8. Well No.		
O'Neill Properties, Ltd.	2		
3. Address of Operator	9. Pool name or Wildcat		
P.O.Box 2840 Midland, Texas 7970 2	Scharb-Bone Springs		
Unit Letter N: 1840 Feet From The West Line and 800	Feet From The South Line		
Section 5 Township 19S Range 35E	NMPM Lea County		
3894 КВ			
11. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data		
	BSEQUENT REPORT OF:		
MOTION TO:	BOEGOENT NEI ONT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLII	NG OPNS. PLUG AND ABANDONMENT X		
PULL OR ALTER CASING CASING TEST AND	CEMENT JOB		
OTHER: OTHER:			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc. work) SEE RULE 1103.	luding estimated date of starting any proposed		
3/9/92 Set 5-1/2" CIBP @ 9500 and cap w/35 sx class "H" cm	t		
3/10/92 Circ hole w/220 bbls. 9.5 mud			
3/10/92 Spot 25 sx H cmt from 7730 to 7504			
3/10/92 Spot 35 sx cmt from 4040 to 3774 (Tag plug @ 3784)			
3/11/92 Spot 35 sx c cmt from 2070 to 1754			
3/11/92 Cut and pull 5½" csg from 1300'			
3/11/92 Spot 45 sx C cmt from 1350 to 1180 (Tag plug @ 1163			
3/11/92 Spot 45 sx C cmt from 1350 to 1180 (Tag plug @ 1163 3/12/92 Perf @ 450 set pkr @ 3801 sqz w/55 sx C cmt)		
3/11/92 Spot 45 sx C cmt from 1350 to 1180 (Tag plug @ 1163 3/12/92 Perf @ 450 set pkr @ 3801 sqz w/55 sx C cmt 3/12/92 Spot 10 sx cmt from 30' to surface	•		
3/11/92 Spot 45 sx C cmt from 1350 to 1180 (Tag plug @ 1163 3/12/92 Perf @ 450 set pkr @ 3801 sqz w/55 sx C cmt	•		
3/11/92 Spot 45 sx C cmt from 1350 to 1180 (Tag plug @ 1163 3/12/92 Perf @ 450 set pkr @ 3801 sqz w/55 sx C cmt 3/12/92 Spot 10 sx cmt from 30' to surface 3/13/92 Cut off wellhead and weld on at steel plate w/dry he	•		
3/11/92 Spot 45 sx C cmt from 1350 to 1180 (Tag plug @ 1163 3/12/92 Perf @ 450 set pkr @ 3801 sqz w/55 sx C cmt 3/12/92 Spot 10 sx cmt from 30' to surface 3/13/92 Cut off wellhead and weld on \(\frac{1}{4}\)" steel plate w/dry holds to surface 3/13/92 Cut off wellhead and weld on \(\frac{1}{4}\)" steel plate w/dry holds to surface 3/13/92 Cut off wellhead and weld on \(\frac{1}{4}\)" steel plate w/dry holds to surface 3/13/92 Cut off wellhead and weld on \(\frac{1}{4}\)" steel plate w/dry holds to surface 3/13/92 Cut off wellhead and complete to the best of my knowledge and belief.	ole marker		
3/11/92 Spot 45 sx C cmt from 1350 to 1180 (Tag plug @ 1163 3/12/92 Perf @ 450 set pkr @ 3801 sqz w/55 sx C cmt 3/12/92 Spot 10 sx cmt from 30' to surface 3/13/92 Cut off wellhead and weld on at steel plate w/dry he	ole marker		
3/11/92 Spot 45 sx C cmt from 1350 to 1180 (Tag plug @ 1163 3/12/92 Perf @ 450 set pkr @ 3801 sqz w/55 sx C cmt 3/12/92 Spot 10 sx cmt from 30' to surface 3/13/92 Cut off wellhead and weld on \(\frac{1}{4}\)" steel plate w/dry holds to surface 3/13/92 Cut off wellhead and weld on \(\frac{1}{4}\)" steel plate w/dry holds to surface 3/13/92 Cut off wellhead and weld on \(\frac{1}{4}\)" steel plate w/dry holds to surface 3/13/92 Cut off wellhead and weld on \(\frac{1}{4}\)" steel plate w/dry holds to surface 3/13/92 Cut off wellhead and complete to the best of my knowledge and belief.	ole marker		

NOV 05'92

DATE -