Form 3160-5 (November 1994) UNITED STATES DEPART NT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			Budget Bure Expires 1	FORM APPROVED Budget Bureau No. 1004-0135 Expires November 30, 2000	
SUNDRY NOTICES AND REPORT ON OWEGENS. Division				5. Lease Serial No.	
Do not use this form for proposals to 1/825. N. Stepch Dr				LC 068037 6. If Indian, Allottee or Tribe Name	
abandoned well. Use	Form 3160-3 (ARD) for such p HODDS, I	MM*88240	N/A		
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or CA/Ag	7. If Unit or CA/Agreement, Name and/or No. NM 061P3584C426	
Type of Well Oil Well Gas Well Other Other				8. Well Name and No. Mescalero 29 1	
Gruy Petroleum Management Co.			Federal Com	Federal Com	
3a. Address 3b. Phone No. (include area code)			9. API Well No.		
P.O. Box 140907 469-420-2728		<u>30-025-28283</u> 10. Field and Pool, c	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Desc	- /		Quail Ridge		
Section 29, T-19-S, R-34-E Unit K 1980 FSL & 1650 FWL			11. County or Parish	11. County or Parish, State	
12. CHECK APPROP	RIATE BOX(ES) TO INDICATE			<u>NM</u>	
TYPE OF SUBMISSION				A	
		TYPE OF AC			
X Notice of Intent	X Acidize	Deepen Pro	duction (Start/Resume)	Water Shut-Off	
Subsequent Report	Alter Casing	Fracture Treat Rec	lamation	Well Integrity	
Subsequent Report	X Casing Repair	New Construction Rec	complete X	Other Add Morrow	
Final Abandonment Notice	Change Plans F	Plug and Abandon Ten	porarily Abandon Pe	rforations	
	Convert to Injection	lug Back Wat	er Disposal		
13. Describe Proposed or Coommpleted Operation (c If the proposal is to deepen directionally or reco Attach the Bond under which the work will be following completion of the involved operations. testing has been completed. Final Abandonmen- determined that the final site is ready for final inspi- Gruy Petroleum Management Co. and stimulate all perforations	performed or provide the Bond No. o If the operation results in a multiple Notices shall be filed only after all sction.) respectfully request ap	n file with BLM/BIA. Requir completion or recompletion in requirements, including recla	red subsequent reports shall o a new interval, a Form 31 mation, have been complete	be filed within 30 days 60-4 shall be filed once d, and the operator has	
Procedure and wellbore skemati	cs are attached				
FICTURE CAN WEILOTE SKELLT	cs are attached.		APPRO JAN 14 GARY GOUL PETROLEUM EI	2003 RLEY	
			Į.		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Don Aldridge	Alchielge Title Date	Sr. Regulatory	Analsyt	LD HODDS OCD	
ТНІ	S SPACE FOR FEDERAL OR				
Approved by		itle			
Conditions of approval, if any, are attached. Approval certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations thereon	of this notice does not warrant or O	ffice	Date		
Title 18 U.S.C. Section 1001, makes it a crime for any fraudulent statements or representations as to any matter with	 person knowingly and willfully to r thin its jurisdiction. 	nake to any department or ag	ency of the United States	any false, fictitious or	
(Instructions on reverse)					

5 C

RECOMMENDED WELLWORK PROCEDURE MESCALERO 29 FED COM #1 QUAIL RIDGE (MORROW) LEA COUNTY, NEW MEXICO

WELL DATA

SPUD DATE:	7/19/83
PERM. ZERO PT.:	KB=3688', GL=3668.7'
TOTAL DEPTH:	13,680'
PBTD :	13,485' (fill)
SURFACE CSG:	13-3/8", 48#, H-40 @ 400'
INTER CSG :	8-5/8", 24 & 28#, J-55 & S-80 @ 5000'
PROD CSG:	5-1/2", 17 & 20#, P-110, S-95, L-80 & N-80 @ 13,680'
PERFS:	13073-13082, 13267-13270, 13276-13282, 13332-13342 & 13505-13521
TBG:	2-3/8" N-80
PKR:	Baker Mod R @ 12954'
OTHER:	Apparent csg leak

OBJECTIVE: The Upper Morrow intervals in this well were never stimulated. A recent BHP showed 3226 psi. Recommend repairing the casing leak, opening up additional pay and stimulating the Morrow to return the well to production.

**** SAFETY IS TOP PRIORITY ****

PROCEDURE:

Use 7% KCL wtr.

- 1. MIRU wellservice rig. Load tbg. ND WH. NU BOP's and test.
- 2. Rls pkr & POH.
- 3. PU & RIH w/ 5-1/2" RBP & pkr on 2-7/8" workstring to 13000'.
- 4. Test csg from 13000' up isolating all leaks. Casing will need to hold 2000 psi during frac job.
- 5. Spot sand on RBP. Sqz leaks as necessary from bottom up. Drill out and test casing.
- 6. Lower & clean out fill from 13485' to PBTD 13580'. POH.
- MIRU e-line. Install lubricator. RIH w/ csg gun and GR/CCL tools. Run strip log to get on depth. Perforate the Morrow 13210-13217', 2 spf by Gearhart Compensated Density Compensed Neutron Log (Run #2) dated 9/6/83 which correlates flat to Schlumberger CBL/Variable Density/CCL log dated 10/8/83. RD e-line.

- RIH w/ 10k RBP & pkr on 2-7/8" workstring. Set RBP +/- 13540' and test. PU & set pkr +/-13480'. Load tbg and EIR into perfs 13505-13521' w/ 5 bbls 7% KCL wtr. SI. Record ISIP and 15 min shut-in pressure.
- Rls pkr. Lower & latch RBP. PU & reset RBP +/- 13360'. Test RBP. PU & set pkr +/-13310'. Load tbg. BD & EIR into perfs 13332-13342' w/ 5 bbls 7% KCL wtr. SI. Record ISIP and 15 min SIP.
- Rls pkr. Lower & latch RBP. PU & reset RBP +/- 13310'. Test RBP. PU & set pkr +/-13240'. Load tbg. BD & EIR into perfs 13267-13282' w/ 5 bbls 7% KCL wtr. SI. Record ISIP and 15 min SIP.
- 11. Rls pkr. Lower & latch RBP. PU & Reset RBP +/- 13240'. Test RBP. PU & set pkr +/-13180'. Load tbg. BD & EIR into perfs 13210-13217' w/ 5 bbls 7% KCL wtr. SI. Record ISIP and 15 min SIP.
- 12. Rls pkr. Lower & latch RBP. PU & Reset RBP +/- 13110'. Test RBP. PU & set pkr +/-13040'. Load tbg. BD & EIR into perfs 13073-13082' w/ 5 bbls 7% KCL wtr. SI. Record ISIP and 15 min SIP.
- 13. Evaluate breakdown pressure, ISIP and 15 min SIP of all zones to determine if frac proposal should be revised to frac only 13073-13342'.
- 14. Rls pkr & POH laying down 2-7/8" workstring.
- 15. PU & RIH w/ pkr on 3-1/2" workstring (csg leak sqz work to determine if mix of P-110 and L-80 is required). Set pkr +/- 12950'. Load & test annulus.
- 16. ND BOP's. NU wellhead. Install wellhead isolation tool.
- 17. MIRU BJ Services pumping, N2 and CO2 equipment. Install pump and pop-off set for 2500 psi on annulus. Stake and tie-down all lines. Pressure test lines to 11000 psi.
- 18. Frac Morrow 13073-13521' w/ 59,000 gals Binary foam and 60,000 lbs 20/40 Interprop dwn 3-1/2" tbg @ 20 BPM (est 9000 WHTP) as follows:
 - a. Pump 3000 gals binary foam pre-pad
 - b. Pump 20000_gals_binary_foam-pad
 - c. Pump 6000 gals binary foam w/ 0.5 ppg 20/40 Interprop
 - d. Pump 9000 gals binary foam w/ 1.0 ppg 20/40 Interprop
 - e. Pump 15000 gals binary foam w/ 2.0 ppg 20/40 Interprop
 - f. Pump 6000 gals binary foam w/ 3.0 ppg 20/40 Interprop
 - g. Flush short of top perf w/ binary foam

Bring annulus pressure up to 2000 psi as pressure on tubing increases.

19. RD BJ Services.

- 20. Open well and flowback till pressure drops below wellhead working pressure. RD wellhead isolation tool.
- 21. Open well and flow test.
- 22. Load tbg. ND wellhead. NU BOP's.
- 23. Rls pkr & POH w/ 3-1/2" workstring laying down.
- 24. PU & RIH w/ pkr & on-off tool on 2-3/8" production tbg. Set pkr +/- 12,950'. Rls from pkr. Rev annulus w/ pkr fluid. Latch pkr. Test annulus.
- 25. ND BOP's. NU wellhead.

26. Swab well in to flow.

27. RD&RR.

28. Open well and flow to test.



