

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

10. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Superior Oil Company, The	6. Farm or Lease Name Mescalero Ridge A Com.
3. Address of Operator P.O. Box 3901, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM <u>East</u> THE <u>West</u> LINE, SECTION <u>17</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> N.M.P.M.	10. Field and Pool, or Wildcat Scharb-Bone Spring
15. Elevation (Show whether DF, RT, GR, etc.) 3822.7' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Recap of P & A Procedure

1. Load hole w/9.5# gelled brine, POH w/prod. equip.
2. Spot 450' plug using 75 sx of class H cmt (50% excess). Displace cmt w/gelled 9.5# brine. WOC, tag TOC.
3. Cut 5-1/2" csg at free point and POH.
4. Spot 150' (75sx at 50% excess) class H cmt plug on top of 5-1/2" csg (75' inside csq, 75' inside open hole). Displace cmt w/9.5# gelled brine. WOC, tag TOC.
5. Spot 150' (105 s at 50% excess) class H neat cmt plug on top of Delaware Mountain Group (6048') from 5973-6123'. Displace w/9.5# brine. WOC, tag TOC.
6. Spot 100' (93 sx at 50% excess) class C neat cmt plug at 9-5/8" csg shoe (4100') from 4050-4150' (50' inside csq, 50' in open hole). Displace w/9.5# gelled brine. WOC, tag TOC.
7. Spot 50' (25 sx at 50% excess) class C cmt plug at surface.
8. Cut csq off 3' below ground level, weld on steel plate w/4' marker above ground.
9. Level cellar and location.

100' PLUG @ 450'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] E. Tate TITLE Division Oper. Superintendent DATE 10-30-84

APPROVED BY [Signature] TITLE DATE NOV - 2 1984

CONDITIONS OF APPROVAL, IF ANY: