

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-29167</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name BRIDGES-STATE
8. Well No. 197
9. Pool name or Wildcat VACUUM GRAYBURG/SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-4014

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Mobil Producing Tx. & N.M. Inc.*
3. Address of Operator *Mobil Exploration & Producing U.S. Inc., as Agent for Mobil Producing TX. & N.M. Inc., P. O. Box 633, Midland, TX 79702	4. Well Location Unit Letter <u>E</u> : <u>2630</u> Feet From The <u>NORTH</u> Line and <u>1310</u> Feet From The <u>WEST</u> Line Section <u>24</u> Township <u>17S</u> Range <u>34E</u> NMPM LEA County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-4014	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SEE ATTACHED PROCEDURES

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kaye Pollock TITLE REGULATORY TECHNICIAN DATE 10-06-92
TYPE OR PRINT NAME KAYE POLLOCK TELEPHONE NO. (915) 688-2584

(This space for State Use)

ORIGINAL SIGNED BY JERRY SERRANO
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE OCT 08 1992

CONDITIONS OF APPROVAL, IF ANY:


NOTE: THE NEW MEXICO OIL CONSERVATION DIVISION (NMOCD) MUST BE NOTIFIED IN HOBBS (505-393-6161) AT LEAST 24 HOURS PRIOR TO ANY PLUGGING OPERATIONS.

PROCEDURE

1. MIRU MAYO MARRS OR EQUIVALENT. POH W/ RODS AND PUMP. ND WH. NU BOP.. MI 2-3/8" WS.
2. RELEASE TAC AT 4553'. POH W/ SAME.
3. RIH W/ 5-1/2" CIBP (5-1/2", 14#/FT CSG) ON 2-3/8" WS AND SET AT $\pm 4450'$. DUMP 35 FT CMT.
4. RUN FREE POINT ON 5-1/2" CSG. IF CSG RECOVERY IS BETWEEN 1600 - 1725 FT, PROCEED AS FOLLOWS, OTHERWISE GO TO STEP #9.
5. CIRC HOLE W/ 10#/GAL GELLED BRINE. SPOT A BALANCED PLUG OF 22 SX CL C NEAT CMT FROM 2950' TO 2735' AND WOC. TAG TOP OF PLUG AT $\pm 2735'$.
6. SET 8-5/8" CMT RETAINER 30 FT ABOVE 5-1/2" CSG STUB AND SQZ 35 SX CMT. DUMP 15 SX CMT ABOVE CMT RETAINER.
7. SPOT CL C NEAT CMT FROM 100' TO SURFACE. POH W/ WS. MAKE SURE CMT IS TO TOP OF PIPE.
8. ND BOP. RD PULLING UNIT. CUT CASING 3' BELOW GROUND LEVEL. WELD A STEEL PLATE ON THE CASING STUB. ERECT P & A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.
9. CUT AND RECOVER 5-1/2" CSG 50 FT ABOVE FREE POINT. IF UNABLE TO RECOVER ANY CSG, GO TO STEP #18.
10. CIRC HOLE W/ 10#/GAL GELLED BRINE. SPOT A BALANCED PLUG OF 22 SX CL C NEAT CMT FROM 2950' TO 2735' AND WOC. TAG TOP OF PLUG AT $\pm 2735'$.
11. PERF 5-1/2" CSG AT 1630 FT.
12. SET 5-1/2" CMT RETAINER AT 1600 FT.
13. STING INTO RETAINER AND SQZ W/ 35 SX CMT.
14. SPOT 10 SX CMT ABOVE RETAINER.
15. SPOT CL C NEAT CMT FROM 50 FT BELOW 5-1/2" CSG STUB TO 50 FT ABOVE STUB.
16. SPOT CL C NEAT CMT FROM 100' TO SURFACE. POH W/ WS. MAKE SURE CMT IS TO TOP OF PIPE.
17. ND BOP. RD PULLING UNIT. CUT CASING 3' BELOW GROUND LEVEL. WELD A STEEL PLATE ON THE CASING STUB. ERECT P & A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.
18. CIRC HOLE W/ 10#/GAL GELLED BRINE. SPOT A BALANCED PLUG OF 22 SX CL C NEAT CMT FROM 2950' TO 2735' AND WOC. TAG TOP OF PLUG AT $\pm 2735'$.
19. PERF 5-1/2" CSG AT 1630 FT.
20. SET 5-1/2" CMT RETAINER AT 1600 FT.
21. STING INTO RETAINER AND SQZ W/ 35 SX CMT.
22. SPOT 10 SX CMT ABOVE RETAINER.
23. SPOT CL C NEAT CMT FROM 100' TO SURFACE. POH W/ WS. MAKE SURE CMT IS TO TOP OF PIPE.
24. ND BOP. RD PULLING UNIT. CUT CASING 3' BELOW GROUND LEVEL. WELD A STEEL PLATE ON THE CASING STUB. ERECT P & A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.


NOTE: P & A PROCEDURE DISCUSSED WITH RAY SMITH AT NMOCD ON OCTOBER 2, 1992.

BRIDGES STATE
WELL NO. 197
VACUUM (GRAYBURG/SAN ANDRES) FIELD
PROPOSED COMPLETION



ALS 10/05/92
FILENAME: BS197P.DRW

BRIDGES STATE
WELL NO. 197
VACUUM (GRAYBURG/SAN ANDRES) FIELD
CURRENT COMPLETION



ALS 9/25/92
FILENAME: BS197C.DRW