VALUE OF OPERATOR P. O. BOX 1861, Midland, TX 79702 10. FIELD AND POOL, OR WILDCAY OUT OF THE OPERATOR OF THE OPERATOR OF WITH ANY STATE PEQUIPMENERS.* Unit Ltr. K. 1980' FSL & 1980' FWL VALUE OF OPERATOR OF THE OPERATOR OF THE OPERATOR OF OPERATOR OPERATOR OF OPERATOR OPERA		NOTICES AND REPORTS for proposals to drill or to deepen or plu "APPLICATION FOR PERMIT—" for suc	ON WELLS ug back to a different reservoir. ch proposals.)	M-60789 NDIAN, ALLOTTEE OR TRIBE NAME
Sun Exploration & Production Co. AREA B. FARTH MITTER NAME Lea Chapparral Fed. Co Whall No. Unit Ltr. K. 1980' FSL & 1980' FWL LYERMIT NO. 15. REPAIRING (Show whether Dr. NT. CH. CH.) 3662.6' GR Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT WILL SPILE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT WILL SPILE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT WILL SPILE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT WILL SPILE OF INTENTION TO: TOTAL CHAPGE PLANE CHAPGE PLANE CHAPGE PLANE CHAPGE PLANE SHOW WHILE OF INTENTION TO: SUBBRIGGENT ERFORT OF SEPTIMENT OF THE SHUT-OFF FRACTURE TREATMENT SHOOT OR ACIDIZE ABANDON' SHOOT OR ACIDIZE ALTERNIC CARNO ALTERNIC CARNO ALTERNIC CARNO ALTERNIC CARNO ALTERNIC CARNO ALTERNIC CARNO SHOOT OF TRAINING WELL ACID TO THE TO THE TO THE TRAINING WELL ALTERNIC CARNO SHOOT OF TRAINING WILL AND SUBBRIC TO THE TRAINING WELL ALTERNIC CARNO SUBBRIC TO THE TRAINING WILL AND SUBBRIC TO THE TRAINING WILL AND SUBBRIC TO THE TRAINING TO THE TRAINING WELL ALTERNIC CARNO SUBBRIC TO THE TRAINING TO THE TRAINING WELL ALTERNIC CARNO SUBBRIC TO THE TRAINING TO THE TRAINING WELL ALTERNIC CARNO SUBBRIC TO THE TRAINING TO THE TRAINING WELL ALTERNIC CARNO SUBBRIC TO THE TRAINING T	OIL GAS X	OTHER	NOV 15	38 MT PREMENT NAME
P. O. Box 1861, Midland, TX 79702 STATUS OF WELL Report location clearly and in accordance with any State requirements.* At surface of 17 below.* Unit Ltr. K. 1980' FSL & 1980' FWL PERMIT NO. 15. FLEVATIONS IShow whether OF, RT. GR. etc.) 16. FLEVATIONS IShow whether OF, RT. GR. etc.) 17. COUNTY OF PARISH 13. STATE 18. GREAT 18. A MODER FLAVA AND STATE 18. STATE 18. GREAT 18. A MODER FLAVA AND STATE 18. STATE 18. GREAT 18. A MODER FLAVA AND STATE 18. STATE 18. GREAT 18. A MODER FLAVA AND STATE 18. STATE 18. GREAT 18. SHOT-OFF PRACTURE TREAT SHOT-OFF PRACTURE TREAT OF ARADONS ARADONS* SHORTING OR ACIDIZED ARADONS* ARADONS ARADONS ARADONS OR COUNTERED OF FRACTURE TREATMENT OF TREATMENT AND SHORTING OR ACIDIZED BASINGER PROCESSED OR COUNTERED OF FRACTURE TREATMENT OF TREATMENT AND SHORTING OR ACIDIZED BASINGER PROCESSED OR COUNTERED OF FRACTURE TREATMENT OF TREATMENT AND SHORTING OR ACIDIZED BASINGER PROCESSED OR COUNTERED OF FRACTURE TREATMENT OF TREATMENT AND SHORTING OR ACIDIZED BASINGER PROCESSED OR COUNTERED OF FRACTURE TREATMENT OF TREATMENT AND SHORTING OR ACIDIZED BASINGER PROCESSED OR COUNTERED OF FRACTURE TREATMENT OF TREATMENT OF TREATMENT OR TREATMENT OF TREATMENT OR TREATMENT OF TREATMENT OR TREATMENT	Sun Exploration	ı & Production Co.	AREA	Lea Chapparral Fed. Co.
Until Ltr. K. 1980' FSL & 1980' FWL 15. PLEVATIONS (Show whether DF, RT, GR, etc.) 3662.6' GR Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOTING OR ACIDIZE ADADON* REPAIR WELL CHANGE PLANF CHANGE PLANF CHANGE PLANF CHANGE PLANF SPOOTING OR ACIDIZE ADADON* REPAIR WELL CHANGE PLANF CHANGE PLANF CHANGE PLANF SPOOTING OR ACIDIZE ADADON* REPAIR WELL CHANGE PLANF CHANGE PLANF COMPLETED OF EXAMPLETED OF SEATIONS (Clerity state all pertinent details, and give pertinent dates, including estimated date of starting any nent to this work.)* Spud 7-19-88 R&C 13 jts. 13-3/8 csg. (61 & 54.5 K) CS 515 Howco mix & pump 135 sxs C w/2% Cacl 2 & 1/4# Flocele mixer went down, Circ cmt to pit circ 2-1/2 hrs waiting on additional cmt. Howco cmt w/525 sx. Cu/2% Cacl 2 1/4# Flocele Test BOP & Casing 100# 0K. R&C 124 jts. 9-5/8 csg. (40#) CS 5300 FC 5255 Stage Collar 3304 circ 1/4 hr. Howco cmt 1st stage w/625 sxs Lite w/10% salt 1/4# Flocele followed by 125 sxs C FP 950-1400 Floats held open stage collar w/1000# circ 4 hr. did not circ cmt. Howco cmt 2nd stage w/1800 sxs Lite w/10% salt & 1/4# Flocele followed by 20 sxs C FP 1000-4500 ran temp sur. TOC 25. R&C 319 jts. 5-1/2 (17 & 20#) CS 13680 Howco cmt w/1000 sxs H, 50/50 poz w/2% gel +	P. O. BOX 1861 LOCATION OF WELL (Report See also space 17 below.) At surface	Midland, TX 79702 ocation clearly and in accordance with a	any State requirements.*	1 10. FIELD AND POOL, OR WILDCAT Quail Ridge Morrow
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Notice of Intention to: Subsequent report of: WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) CHANGE PLANS CHANGE PLANS (Other) CHANGE PLANS CHANGE PLANS (Other) (Other) CHANGE PLANS (Other) CHANGE PLANS (Other) CHANGE PLANS (Other) (Other) CHANGE PLANS ALTERING CABING ALTERIOTA ALTERIOTA ALTERIOTA ALTERIOTA ALTERIOTA ALTERIO	Unit Ltr. K. 19	80' FSL & 1980' FWL		11. SEC., T., E., M., OR BLK, AND SURVEY OR ARMA
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Notice of Intention to: Subsequent emport of: WATER SHUT-OFF PRACTURE TREAT SHOOTING OR ACIDIZE REPAIR WELL CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS COther) Casing Information (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Note: Report results of multiple completion on Well Completion or Recompletion on Report and Log form.) (Note: Report results of multiple completion on Well Completion or Recompletion or Recompletion on Report and Log form.) (Note: Report results of multiple completion on Well Completion or Recompletion or Recompletion or Rec	. PERMIT NO.	1	DF. RT. GR. etc.)	12. COUNTY OR PARISH 13. STATE
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL CHANGE PLANS CHANGE PLANS CHANGE PLANS CHORE TREAT SHOOT OR ACIDIZE REPAIR WELL CHANGE PLANS CHANGE TREATMENT ALTERING CSING ABANDONNET ALTERING CSING ABANDONNET ALTERING CSING ABANDONNET CONTEXT. ALTERING CSING ABANDONNET ALTERING CSING ABANDONNET CONTEXT. ALTERING CSING ABANDONNET ALTERING CSING ABANDONNET CONTEXT. ALTERING ALTERING CSING ABANDONNET ALTERING	Ch	eck Appropriate Box To Indicate	Nature of Notice, Report, or O	ther Data
SHOOT OF ACIDIZE SHOOT OF ACIDICE SHOOT	NOTICE	OF INTENTION TO:	1	
Spud 7-19-88 R&C 13 jts. 13-3/8 csg. (61 & 54.5 K) CS 515 Howco mix & pump 135 sxs C w/2% Cacl 2 k1/4# Flocele mixer went down, Circ cmt to pit circ 2-1/2 hrs waiting on additional cmt. Howco cmt w/525 sx. Cu/2% Cacl 1/4# FloceleTest BOP & Casing 100# OK. R&C 124 jts. 9-5/8 csg. (40#) CS 5300 FC 5255 Stage Collar 3304 circ 1/4 hr. Howco cmt 1st stage w/625 sxs Lite w/10% salt 1/4# Flocelefollowed by 125 sxs C FP 950-1400 Floats held open stage collar w/1000# circ 4 hr. did not circ cmt. Howco cmt 2nd stage w/1800 sxs Lite w/10% salt & 1/4# Flocelefollowed by 200 sxs C FP 1000-4500 ran temp R&C 319 jts. 5-1/2 (17 & 20#) CS 13680 Howco cmt w/1000 sxs H, 50/50 poz w/2% gel + 2% KCL + .3% CFR-2 + .5% Halad 220 Tailed in w/1000 sxs H, 50/50 poz w/2% gel +	FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	MULTIPLE COMPLETE ABANDON®	PRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING
Spud 7-19-88 R&C 13 jts. 13-3/8 csg. (61 & 54.5 K) CS 515 Howco mix & pump 135 sxs C w/2% Cacl & 1/4# Flocele mixer went down, Circ cmt to pit circ 2-1/2 hrs waiting on additional cmt. Howco cmt w/525 sx. Cu/2% Cacl 1/4# FloceleTest BOP & Casing 100# OK. R&C 124 jts. 9-5/8 csg. (40#) CS 5300 FC 5255 Stage Collar 3304 circ 1/4 hr. Howco cmt 1st stage w/625 sxs Lite w/10% salt 1/4# Flocelefollowed by 125 sxs C FP 950-1400 Floats held open stage collar w/1000# circ 4 hr. did not circ cmt. Howco cmt 2nd stage sur. TOC 25. R&C 319 jts. 5-1/2 (17 & 20#) CS 13680 Howco cmt w/1000 sxs H, 50/50 poz w/2% gel + 2% KCL + .3% CFR-2 + .5% Halad 220 Tailed in w/1000 sxs H, 50/50 poz w/2% gel +	DESCRIPE UROMANER OR OTHER	ETED OPERATIONS (Clearly state all mark)		UUU TLEDOFF ADd Loo form \
cmt. Howco cmt w/525 sx. Cu/2% Cacl ₂ 1/4# FloceleTest BOP & Casing 100# OK. R&C 124 jts. 9-5/8 csg. (40#) CS 5300 FC 5255 Stage Collar 3304 circ 1/4 hr. Howco cmt 1st stage w/625 sxs Lite w/10% salt 1/4# Flocelefollowed by 125 sxs C FP 950-1400 Floats held open stage collar w/1000# circ 4 hr. did not circ cmt. Howco cmt 2nd stage w/1800 sxs Lite w/10% salt & 1/4# Flocelefollowed by 200 sxs C FP 1000-4500 ran temp R&C 319 jts. 5-1/2 (17 & 20#) CS 13680 Howco cmt w/1000 sxs H, 50/50 poz w/2% gel + 2% KCL + .3% CFR-2 + .5% Halad 220 Tailed in w/4000 sxs C FP	nent to this work.) *			copies for an markers and zones perti-
R&C 124 jts. 9-5/8 csg. (40#) CS 5300 FC 5255 Stage Collar 3304 circ 1/4 hr. Howco cmt 1st stage w/625 sxs Lite w/10% salt 1/4# Flocele followed by 125 sxs C FP 950-1400 Floats held open stage collar w/1000# circ 4 hr. did not circ cmt. Howco cmt 2nd stage w/1800 sxs Lite w/10% salt & 1/4# Flocele followed by 200 sxs C FP 1000-4500 ran temp R&C 319 jts. 5-1/2 (17 & 20#) CS 13680 Howco cmt w/1000 sxs H, 50/50 poz w/2% gel + 2% KCL + .3% CFR-2 + .5% Halad 220 Tailed in w/400 sxs C FP 1007-100 poz w/2% gel +				
R&C 319 jts. 5-1/2 (17 & 20#) CS 13680 Howco cmt w/1000 sxs H, 50/50 poz w/2% gel + 2% KCL + .3% CFR-2 + .5% Halad 22A, Tailed in w/400 sxs Class H 50/50 poz w/2% gel + 2% KCL+.3% CFR-2. + .5% Halad 22A + .6% Gas stop FP 2500-3090# Ran Temp Sur. TOC 8100'	R&C 13 jts. 13-3 1/4# Flocele mix cmt. Howco cmt	N/525 sx. Cu/2% Cacl ₂ $1/4$	4# FloceleTest BOP & Cas	ting on additional . Sing 100# OK
	R&C 13 jts. 13-3 1/4# Flocele mix cmt. Howco cmt w R&C 124 jts. 9-5 cmt 1st stage w/o Floats held open	w/525 sx. Cu/2% Cacl ₂ 1/4/8 csg. (40#) CS 5300 F(625 sxs Lite w/10% salt i	4# FloceleTest BOP & Cas C 5255 Stage Collar 3304 1/4# Flocelefollowed by	sing on additional sing 100# OK. circ 1/4 hr. Howco 125 sxs C FP 950-1400

(This space for Federal or State office use) ACCEPTED FOR RECORD APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY: TITLE

DEC 6 1988

11 -11-88

eggin odi

*See Instructions on Reverse Side

Accountant

CARLSBAD, NEW MEXICO