

BUREAU OF LAND MANAGEMENT		NM-17807	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different formation. See "APPLICATION FOR PERMIT" for such proposals.)		1. IF PERMIT, ALLOTTEE (or other name)	
2. DATE OF NOTICE DATE		3. DATE OF NOTICE DATE	
NAME OF OPERATOR Siete Oil & Gas Corporation		4. NAME OF LAND NAME Quanah Federal	
ADDRESS OF OPERATOR P.O. Box 2523 Roswell, NM 88202-2523		5. WELL NO. 1	
LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also notes 11 below.) At surface 330' FSL & 2310' FWL, SE $\frac{1}{4}$ SW $\frac{1}{4}$, Unit Letter N		10. FROM AND TO, ON WIRECAT Young-Wolfcamp <i>Querecho Plain upper B 5</i>	
11. SEC. T. R. N. ON BLM. AND COUNTY OR AREA Sec. 14: T18S, R32E		12. COUNTY OR PARISH Lea	
13. STATE NM		14. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	WELL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZING ☐	ABANDON ☐	SHOOTING OR ACIDIZING ☒	ABANDONMENT ☐
REPAIR WELL ☐	CHANGE PLANE ☐	(Other) ☐	(Other) ☐
(Note: Report results of multiple completions on Well Completion or Recombination Report and Log form.)			

Describe proposed or completed operations (Clearly state all pertinent details, and give pertinent data including estimated date of starting any proposed work. If well is directionally drilled, give subsurface boundaries and measured and true vertical depths for all markers and open parts from to this work.)

10/13/88 RU Schlumberger, GIH w/CIBP on wireline, set CIBP @ 10800', POOH w/wireline & setting tool, GIH w/4" casing gun, perforate interval 10216'-10244' w/14 perforations, TIH w/tbg & treating pkr, SION

10/14/88 Spot 2 bbls acid across perfs, set pkr @ 10127', load backside, pressure to 960 PSI, formation broke @ .2 BPM @ 5500 PSI, open bypass, displace acid to 10127', closed bypass, start acid @ 1 BPM @ 4270 PSI, increased to 2.5 BPM @ 3960 PSI, increased to 3 BPM @ 4330 PSI, increased to 4 BPM @ 4100 PSI, AIR-4 BPM @ 3600 PSI, balled out to 5400 PSI, surge, finish flush, well on vacuum @ surging balls, begin swabbing.

RECEIVED
NOV 11 11 32 AM '88
CARLSBAD, NEW MEXICO

I hereby certify that the foregoing is true and correct

SIGNED Cathy Batley TITLE Drilling/Production Secretary DATE 10/27/88

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY _____ TITLE _____ DATE NOV 1 1988

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

RECEIVED

FEB 16 1990

OCD
HOBBS OFFICE