

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		5. LEASE DESIGNATION AND SERIAL NO. <u>NM-56749</u>
2. NAME OF OPERATOR <u>Texaco Producing Inc</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P.O. Box #3109 Midland Tx 79702</u>		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>1980' FNL & 1675' FEL</u> <u>Unit #</u>		8. FARM OR LEASE NAME <u>Federal (USA) 2"</u>
14. PERMIT NO. API No. <u>30-025-30685</u>		9. WELL NO. <u>3</u>
15. ELEVATIONS (Show whether DP, RT, GR, etc.) <u>GR-3687</u>		10. FIELD AND POOL, OR WILDCAT <u>Tonto, Seven Rivers</u>
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 14 T-19-S R-33-E</u>
NOTICE OF INTENTION TO:		12. COUNTY OR PARISH / 13. STATE <u>Lea / NM</u>
TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐ FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐ SHOOT OR ACIDIZE ☐ ABANDON* ☐ REPAIR WELL ☐ CHANGE PLANE ☐ (Other) ☐		SUBSEQUENT REPORT OF: WATER SHUT-OFF ☐ REPAIRING WELL ☐ FRACTURE TREATMENT ☐ ALTERING CASING ☐ SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐ (Other) <u>Commercial Completion</u> (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU X-Perf Well Service. NU BOP & Test 5 1/2 CSG w/ 3000 psi 8:15 to 8:45 AM 11-8-89.
 Perforate Run GR-CCL from 4060 to 3000'. Perf Seven Rivers in interval of:
 3820-3826, 3841-3856. Total 42 holes. TTH w/ pkr & set @ 3706. Swab test.
 (2 JSPF)
 Acidize perfs by Dowell w/ 2500 gals 7 1/2% NEFE w/ 65 Ball Sealers. Swab test.
 ToH w/ pkr. TTH w/ RBP AND set @ 3775. ToH w/ 1bg. Perforate interval of: 3701-3718
 total of 34 holes. TTH w/ pkr. Swab test. By Dowell Acidize perfs w/ (2 JSPF)
 1500 gals 7 1/2% NEFE. w/ 50 BALL Sealers. Swab test. By Western FRAC perfs
 @ 3701-18 w/ 31,000 gals 40# X-Linked gel w/ 35,000# 20/40 SAND & 12,500# 12/20
 RESIN COATED SAND. Swab test. ToH w/ pkr & TTH w/ production 1bg. SN @ 3720.
 RTH w/ 2 1/2 x 1 1/2 x 20' pump & Rods. Hang on beam AND place on pump.
 OPT well 11-26-89. 29 BNO, 25 BLW, 33.3 MCF, 1148 GOR, GRAVITY 39.4 @ 60°.

18. I hereby certify that the foregoing is true and correct

SIGNED C. P. [Signature]TITLE Drilling SuperintendentDATE 12-6-89

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

ACCEPTED FOR RECORD

Admin

*See Instructions on Reverse Side

DEC 12 1989