

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30906
5. Indicate Type of Lease	STATE <input type="checkbox"/> FILE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		7. Lease Name or Unit Agreement Name
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	E. D. Shipp	
2. Name of Operator Lynx Petroleum Consultants, Inc.	8. Well No. 1	
3. Address of Operator P. O. Box 1979, Hobbs, NM 88241	9. Pool name or Wildcat Midway San Andres	
4. Well Location Unit Letter <u>C</u> : <u>330</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>20</u> Township <u>17S</u> Range <u>37E</u> NMPN <u>Lea</u> County		
10. Elevation (Show whether DF, RKB, RT, GK, etc.) <u>3786' KB</u>		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2/3/92 RU and pull rods.
- 2/4/92 Install BOP. Pull tubing. Set CIBP at 5050'. Circulate mud. Spot 5 sxs cement from 5050-5000'. Pull 34 jts. tubing.
- 2/5/92 Pull tubing. Weld on lift nipple. Run free point on casing - free at 1100'. Work casing free to 1600'. Cut casing at 2700'. Try to work loose - cannot pull casing. Run tubing back to 2750'. Spot 20 sxs of cement from 2750-2560'.
- 2/6/92 Pull tubing. Cut and pull casing at 1600'. Run in hole with tubing to 1650'. Spot 35 sxs cement from 1650-1500'. WOC 4 hrs. Tag cement at 900'. Openhole fell in. Cannot get down to tag cement. Pull to 454'. Spot 35 sxs cement.
- 2/7/92 Tag cement at 350'. Pull to 60'. Circulate 15 sxs of cement from 60'-surface. Cut off wellhead. Install marker. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marc L. Wise TITLE President DATE 5/7/92
TYPE OF PRINT NAME Marc L. Wise TELEPHONE NO 392-6950

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JUL 15 '92
CONDITIONS OF APPROVAL, IF ANY

RECEIVED

MAY 11 1992

OCD HOBBS OFFICE