

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-30970

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

B-1056-1

7. Lease Name or Unit Agreement Name

VACUUM GLORIETA WEST UNIT

8. Well No.

48

9. Pool Name or Wildcat

VACUUM GLORIETA

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL ☒ WELL GAS ☐ WELL OTHER ☐

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator

P.O. BOX 730, HOBBS, NM 88240

4. Well Location

Unit Letter P : 815 Feet From The SOUTH Line and 800 Feet From The EAST Line

Section 25 Township 17S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER:

ADD PAY AND ACIDIZE ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. TOH W/ PROD EQUIP. TAG @ 6299' (PBDT) & C/O IF NECESSARY. SET RBP @ +6290' & SET PKR @ 6169', LOAD BS W/ FW & TEST TO 300 PSI FOR 30 MIN.

2. ACIDIZE PERFS FR 6166'-6175' W/ 1500 GALS 20% NEFE HCL, MAX P = 3800#, AIR = 4 BPM. SI 1 HR, SWAB BACK.

3. RETRIEVE RBP & SET @ 6100', SPT 4 BBLs ACETIC ACID, TOH W/ PKR.

4. RUN GR/CORRELATION LOG. PERF W/ 2 SPF FR 5995'-6050' (56FT - 112 HLES).

5. SPT 150 GALS 20% NEFE HCL FR 6050'-5995', SET PKR @ 5776', SQZ ACID INTO FORMATION, SI 1 HR, SWAB BACK.

6. LOAD BS W/ FW. ACIDIZE PERFS FR 5995'-6050' W/ 5500 GALS 20% NEFE HCL, MAX P = 3800#, AIR = 4 BPM. SI 1 HR. SWAB BACK.

7. RETRIEVE RBP & PKR. TIH W/ PROD EQUIPMENT & RETURN WELL TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Monte C. Duncan

TITLE Engr Asst

DATE 5/18/94

TYPE OR PRINT NAME

Monte C. Duncan

Telephone No. 397-0418

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Orig. signed by
Paul Soto
Geologist

M. 20 94

RECEIVED

MAY 19 1994

**GOODHOODS
OFFICE**