

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32435
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VB-0333

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'  
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER DRY	7. Lease Name or Unit Agreement Name STATE "P"
2. Name of Operator XERIC OIL & GAS CORPORATION	8. Well No. 1
3. Address of Operator P.O. Box 51311 Midland, TX 79710	9. Pool name or Wildcat Wildcat (San Andres)
4. Well Location Unit Letter <u>0</u> : <u>550</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>19-S</u> Range <u>34-E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3974 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 4-1/2" CIBP above perforations (5646-58) and cap w/ 5 sxs.
2. Circulate hole with plug mud.
3. Find 4-1/2" casing free pt. and cut @ approx. 3600' and pull out.
4. Spot 25 sxs across casing stub.
5. Find 8-5/8" casing free pt. @ approx. 2228', cut and pull out.
6. Spot 30 sxs across casing stub.
7. Spot 30 sxs across salt section.
8. Spot 10 sxs at surface.
9. Cut off well head, install dry hole marker, close work pit, cut off deadmen and clean location.

100' PLUG ACROSS 13 3/8 CSG SHOG  
\*\* Charles Gilespeie, the previous operator, had already set plug from 8070'-7970' with 35 sxs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joe K. Smith TITLE Geologist DATE 11-18-94  
TYPE OR PRINT NAME Joe K. Smith 915-683-3171 TELEPHONE NO.

(This space for State Use)

APPROVED BY JOHN L. SEXTON TITLE Assistant Secretary DATE 11-18-94  
CONDITIONS OF APPROVAL, IF ANY:

NO. 11-18-94  
NO. 11-18-94  
NO. 11-18-94  
NO. 11-18-94