Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89		
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240 DISTRICT II	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		<b>Well Api no.</b> 30-025-32844		
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			5. Indicate Type of Lease STATE X FEE		
SUNDRY NOT					
( DO NOT USE THIS FORM FOR PRI DIFFERENT RESE (FORM C	7. Lease Name or Unit Agreement Name State 'A'				
1. Type of Well: OIL GAS WELL K WELL	OTHER	<u>.</u>			
2 Name of Operator Altura Energy LTD			8. Well No. 10		
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294			9. Pool name or Wildcat Vacuum Abo, North		
4. Well Location Unit Letter <u>A</u> : <u>940</u>	) Feet From The North	Line and94(	East Line		
Section 31 Township 17-S Range 35-E NMPM Lea County					
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3973' GL					
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
		REMEDIAL WORK			
	CHANGE PLANS		GOPNS.		
PULL OR ALTER CASING					
OTHER:		OTHER:Plugbay	ck to the Abo		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attached for description of plugback operations.

SKONATURE Mark Stephens		Business Analyst (SG)	DATE8/19/98
TYPE OR PRINT NAME	Mark Stephens		(201) TELEPHONE NO. 552-1158
(This space for State Use)	ORIGINAL SIGNED BY		
APPROVED BY	PIELD REP. 1		DATE
CONDITIONS OF APPROVA			$\mathbf{k}_{\mathrm{iv}}$

State 'A' Well No. 10 API No. 30-025-32844 Lea County, NM

6/17/98 – 7/9/98

MI x RUSU. Kill well and run 3.81 gauge ring. RIH w/CIBP and set at 10,630'. Run bailer x dump 35' cement on top of CIBP. Load x test casing and CIBP (500 psi). RU WL truck and perf well at 9280' – 9295', 9170' – 9185', 8790' – 8800', and 8560' – 8575' (2 JSPF). ND BOP x flange up tree x swab well. RU Dowell and acidize well with 4000 gal. HCL. Continue swabbing. TIH w/RBP x packer and acidize perfs with 5500 gal. HCL. LD RBP & pkr. x TIH with production equipment x tubing. ND BOP, NU wellhead x swab well. Run x space out rods. Load x test x RD. Shut well in and wait to set pumping unit, hook up electricity, and lay flowline.

7/17/98 – Put well on production.

7/23/98 - AWO test: 35 BO x 2 BW x 53 MCF.