

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-33954
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name McCallister State
8. Well No. 12
9. Pool name or Wildcat Vacuum; Atoka
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4008 KB 4026

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator P.O. Box 2409 Hobbs, NM 88240	
4. Well Location Unit Letter 1 : 1945 Feet From The South Line and 850 Feet From The West Line Section 25 Township 17-S Range 34-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4008 KB 4026	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **Place well on Rod Pump** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU pulling unit. RIH & set blanking plug at 10,855'. POOH. ND wellhead. NU BOP. Attempt to release on/off tool at 10,855'. Tool would not release. PLS pkr released. POOH w/ mech/tbg release, nipple, PLS pkr, on/off tool on 2 7/8" L-80 tbg. RIH w/mud jt, SN, 5 jts tbg, 5 1/2" tbg anchor on 345 jts 2 7/8" L-80 tbg. ND BOP. Set anchor. NU wellhead. TAC at 10,901', SN at 11,062'. RIH w/gas anchor, 1 1/4" pump, shear tool on 3/4", 7/8" steel rods and 1.25" GF rods. Seat pump. Hung well on. Load and test tbg to 500 psi. RD pulling unit. Hook up flowline. Start well pumping to battery.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 9/4/97

TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: