f		
NO. OF COPIES RECEIVED	-	Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oll & Gos Leave No.
		E-5886
DO NOT USE THIS FORM FOR PORTUGE MAPPLICA	RY NOTICES AND REPORTS ON WELLS ADDRESS TO BRILL OF TO DEPEN OF FLUG PACK TO A DIFFERENT RESERVOIR. TION FOR FLAMT - " (FORM C-101) FOR SUCH PROPOSALS.)	
1.	,	7. Unit Agreement Non.e
OIL GAS WELL 2. Name of Operator	OTHER. Water Injection Well	West Pearl Queen Unit
Gulf Oil Corporation		8. Furm or Lease Hume
3. Address of Operator	· · · · · · · · · · · · · · · · · · ·	9. W. 11 No.
		5, W. H 100
Box 670, Hobbs, New M	exico 88240	138
	440 ·····	10. Field and Pool, or Wildoat
UNIT LETTERB	660 FEET FROM THE NOTTH LINE AND 1980 FEET	rRohd Pearl Queen
)		
THE East LINE, SECT	10N 32 TOWNSHIP 19-S RANGE 35-E	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3730' GL	Lea
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data		
NOTICE OF I		JENT REPORT OF:
	3083200	JENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND AGANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ASANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
PIUG and Abandon	0THER	
OTHER 1205 GIR IDAILOUI		•
Fished tubing and repaired casing.		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SET RULE 1103.

5021' TD.

Found both string of 1-1/4" tubing stuck. Milled and recovered both strings of tubing to 734'. Found 4-1/2" casing parted at 733'. Ran Bowen lead seal bowl on 4-1/2" OD 10.50# K-55 ST&C casing. Worked over casing stub at 733' and set with 6,000# tension. After an extensive fishing job both strings of 1-1/4" tubing were recovered from 1735'. It is now proposed to plug and abandon as follows, as discussed by Mr. J. T. Sexton and Mr. D. T. Berlin on May 26, 1976: Set cement retainer at approximately 1700' and squeeze **2**00 sacks of cement below retainer. Spot 10 sack, 100', cement plug on top of retainer. Test casing with 500#, 30 minutes. Spot 10 sack, 100', cement plug from 783' to 683', across 4-1/2" casing repair at 733'. Spot 5 sack cement plug from 50' to surface. Install dry hole marker and clean location.

Expires 10/1/76