

N. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-5841

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator	West Pearl Queen Unit
3. Address of Operator	8. Farm or Lease Name
P. O. Box 670, Hobbs, NM 88240	
4. Location of Well	9. Well No.
UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM	10. Field and Pool, or Wildcat
THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>19-S</u> RANGE <u>35-E</u> NMPM.	Pearl Queen
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3719' GL	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOBS ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☒	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5036' TD. Run and set cement retainer at 2550'. Squeeze below cement retainer with 200 sacks Class C plus 5# salt per sack and 2% CaCl₂. Cap cement retainer with 200' Class "C" cement. Test casing to 500#. Circulate abandonment mud. Perforate (2), 1/2" JH at 1600'. Run 4-1/2" packer and establish injection rate. Run 4-1/2" cement retainer and set at approximately 1550'. Squeeze 300 sacks Class "C" cement with 5# salt/sack plus 2% CaCl₂ and cap retainer with 100' cement. Spot 50' cement plug from 50-0'. Install dry hole marker. Clean location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE CLOSURE TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. P. Sikes, Jr. TITLE Area Engineer DATE 11-15-78

Orig. Signed By
Jerry Sexton

APPROVED BY Dist 1, Supv.

CONDITIONS OF APPROVAL, IF ANY:

Expires 5/16/79

DEC -4 1978

WEST PEARL QUEEN UNIT (LEA, NM)
West Pearl Queen Unit No. 147

AUG 28 1978

MIRU X-Pert Well Svc to repair tbg & place on prod. Pld rods & pump. NU BOP. Pld on tbg. Tbg stuck. Wrkd tbg to free up. Tbg parted below upset of top jt. LD rods. ND BOP. NU wellhead. SD ending 7A, 8-10-78. MIRU X-Pert Well SVCU. NU BOP. Ran 3-7/8" overshot on 1 jt 2-3/8" tbg. Work OS over fish approx 15' from surf. Caught fish. P/U on tbg. Tbg stuck. Tbg parted @ 30,000# pull. POH w/81 jts & broken jt. Ran 80 jts. POH & LD 80 jts. SDON & Sunday ending 7A, 8-28-78. MAGEE

WEST PEARL QUEEN UNIT (LEA, NM)
West Pearl Queen Unit No. 147

AUG 29 1978

5030' PB. RU RVSU. Ran 3-7/8" flat bot mill on (4) 3-1/8" DC's & 76 jts of 2-3/8" tbg. Milled 18" off top of fish. POH. Ran 3-7/8" OS on 80 jts of 2-3/8" tbg to 2602'. Did not catch fish. POH. Ran 3-3/4" impress block on tbg. Impress block indicated csg parted. SDON ending 7A, 8-29-78. MAGEE

WEST PEARL QUEEN UNIT (LEA, NM)
West Pearl Queen Unit No. 147

AUG 30 1978

5030' PB. Ran 3-1/4" swage on (1) 3-1/8" DC & 79 jts 2-3/8" tbg. Tagged up @ 2602'. Wrkd swage dn to 2606'. Rotated swage to leave marks. POH. Markings on swage indicated setting dn on tbg. Ran 3-13/16" ext w/mule shoe on bot & 3-13/16" dress-off mill on (4) 3-1/8" DC's & 78 jts 2-3/8" tbg. Tagged up @ 2602'. Std rotating. Bot of shoe moved to 2606'. Milled for 2 hrs. Did not make any hole. Returns show to be potash mud. No metal. POH. SDON ending 7A, 8-30-78. MAGEE

WEST PEARL QUEEN UNIT (LEA, NM)
West Pearl Queen Unit No. 147

AUG 31 1978

5030' PB. Ran 3-13/16" dress-off mill, (4) 3-1/8" DC's & 16 jts of 2-3/8" tbg. Received word to plug well. POH. LD DC's. SDON ending 7A, 8-31-78 MAGEE

WEST PEARL QUEEN UNIT (LEA, NM)
West Pearl Queen Unit No. 147

SEP 01 1978

5030' PB. Ran 80 jts 2-3/8" tbg. POH. LD pipe in singles. ND BOP. NU wellhead. RD X-Pert Well Svc. Rpt ending 7A, 9-1-78. MAGEE

WEST PEARL QUEEN UNIT (LEA, NM)
West Pearl Queen Unit No. 147

SEP 05 1978

5030' PB. COMPLETE after unsuccessful attempt to restore production. CI pending P&A. Rpt ending 7A, 9-5-78. MAGEE - OFF REPORT -

GLE: 3719

KDB: 3729

H = 10

Initial Comp. Date: April 4, 1960
Producing Formation: Pearl Rider

Top salt @ 1800'
Base salt @ 3300'

Zone	Comp. Date	Date Aban
4802-4952	April 4, 1960	

8 5/8" OD 24 # Grade J-55 Treatment History: (Current Zone)
(3-24-60) Trd. perfs 4802-4952 w/

Set @ 153' w/ 100 sxs 1500 gal refined oil

Top of Cmt @ surface, cir by: 10s (4-6-65) Drld deeper from 4980-50

Pumped 500 gal 15% NE HCL

(12-26-72) 1000 gal 15% NE HCL

(8-28-78) RUPU & attempted to pull tbg.

Tbg stuck. Tbg parted. Layed down 81 ft. tbg

Milled on fish. Did not catch fish. Impression

black indicated csg parted. Ran swage.

Ran ext w/ mule shoe & dress off mill.

Milled 2 hrs. No hole made.

DV
@
1893'

Bad pipe indicated
from 2622-2658

Top fish approx 2606
+ tbg. stuck

Producing History:

Formation: _____

Month or Year	Oil	Water	Gas

Last Test Dated: _____

BOPD

BWPD

FL: _____ Calc. Ppg. Eff: _____

Cum. Oil _____ Cum. Gas _____

79 ft. 2 3/8" 4.70 # EUE BRD J-55 + tbg

SN @ 4967

4' perf sub @ 4968

2 3/8" EUE BRD 4.70 # J-55 mud
anchor w/ BPOB. Btm tbg @ 5003

4802-04 } 4 1/2"
4904-06 } JHPF
4950-52 }

4 1/2" OD 9.50 # Grade J-55

Set @ 4980' w/ 250 sxs

Stage 1 3875

Top of Cmt @ Stage 1 11660 by: TS

① 200 sxs 4% gel

③ 50 sxs 4% gel then DV

3 3/4" O.H.

Remarks and Recommendation:

Plug & Abandon

TD 5036

Prepared By: LBJ

Date: 8-30-78