

FEB 27 8 15 AM '67

Plug back and recomplete in San Andres.

1. Pull tubing.
2. Set CIBP at 12,500' & cap w/cement.
3. Determine free point of 7" casing, shoot & pull.
4. Spot the following cement plugs:
  - 50 sx at 7" stub
  - 75 sx at 11,920' (top of Atoka)
  - 50 sx at 11,552' (top of Pennsylvanian)
  - 50 sx at 10,920' (top of Wolfcamp)
  - 50 sx at 7880' (top of Bone Spring)
  - 50 sx 5700' - 5900'
5. Clean open hole to 5500'.
6. Cement 5500' of 7" 26# & 29# casing w/200 sx. Space centralizers at 60' intervals up to 5250'. WOC 36 hrs.
7. Run GR/CCL from PBTD to 5250'.
8. Perforate San Andres at 5320', 5325', 5348', 5359', 5361', 5361', 5385', 5424', w/1 - 3/8" JSPF (total 7 holes).
9. Spot 300 gallons 15% NEA. Set packer at 5200' & treat w/1000 gallons 15% NEA using ball sealers.
10. Treat w/12,000 gallons frac fluid containing 20#/1000 gal Guar Gum + 25#/1000 gal adomite aqua + 1 gal adomal/1000 gal + 1 1/2# 20-40 mesh sand/gallon.
11. Run production equipment.
12. Recover load.
13. Place on production.

