

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

HOBBS OFFICE O. C. C.  
NEW MEXICO OIL CONSERVATION COMMISSION

DEC 1 1 34 PM '65

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator <b>Amerada Petroleum Corporation</b>		8. Farm or Lease Name <b>W. A. Weir</b>	
3. Address of Operator <b>P. O. Box 668 - Hobbs, New Mexico</b>		9. Well No. <b>6</b>	
4. Location of Well UNIT LETTER <b>C</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>35</b> TOWNSHIP <b>19S</b> RANGE <b>36E</b> NMPM.		10. Field and Pool, or Wildcat <b>Monument</b>	
15. Elevation (Show whether DF, RT, GR, etc.) <b>3652' DF</b>		12. County <b>Lea</b>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled rods, pump and tubing. Ran string shots of 100 and 300 grains per foot respectively over perforations from 3938' to 3948'. Ran tubing with packer and holddown. Acidized perforations from 3938' to 3948' with 1000 gals. 15% NE acid using ball sealers. Swab tested. Pulled tubing, packer and holddown. Reran tubing, pump and rods and resumed production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]*

TITLE Asst. Dist. Supt.

DATE 11-23-65

APPROVED BY *[Signature]*

TITLE

DATE 11-23-65

CONDITIONS OF APPROVAL, IF ANY: