	Energy, Minerals and Natural R	lesources Department	Form C-100
District J	OIL CONSERVATIO	Revised 1-1-89	
P.O. Box 1980, Hobbi, NM 82240 DISTRICT 11	P.O. Box 20	88	WELL API NO.
P.O. Drawer DD, Aneria NM \$\$210	Santa Fe, New Mexico	87504-2088	30-025-04126
DISTRICT III 1000 Rio Brizos Rd., Ariec, NM 87+10			S. Indicate Type of Lease STATE FEE
NO DIALOS KG., AMEC, NM \$7410			6 Suis Oil & Cas Lesse No.
SUNDRY NOT	ICES AND REPORTS ON WE	ILLS	
DIFFERENT RESE (FORM C	OPOSALS TO DRILL OR TO DEEPEI RVOR. USE 'APPLICATION FOR PE - 101] FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
	on-ea		NORTH MONUMENT G/SA UNIT
AMERADA HESS CORPORATION			& Well No.
J. Address of Operator	9. Pool same or Wildcat		
4. Well Location	D, MONUMENT, NEW MEXI	CO 88265	EUNICE MONUMENT G/SA
Unit Letter :6	60 Ford From The SOUTH	Line and 19	
			980 Feet From The EAST
Section 35	Township 195 R 10. Elevation (Show whether	ange 36E	NTAPM LEA Cour
			<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
11. Check	Appropriate Box to Indicate	Nature of Notice. R	eport or Other Data
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF
PERFORM REMEDIAL WORK		REMEDIAL WORK	
EMPORARILY ABANDON			L ALIENING LASING
	CHANGE PLANS	COMMENCE DRILLING	
	CHANGE PLANS		GOPNS. D PLUG AND ABANDONMEN
PULL OR ALTER CASING		CASING TEST AND CE	GOPNS. D PLUG AND ABANDONMEN
PULL OR ALTER CASING	tion well. X	CASING TEST AND CE	GOPNS. DPLUG AND ABANDONMEN
PULL OR ALTER CASING	tion well. X	CASING TEST AND CE OTHER:	GOPNS. PLUG AND ABANDONMEN
DULL OR ALTER CASING DTHER: <u>Convert to inject</u> 12 Describe Proposed or Completed Crysta work) SEE RULE 1103. NMGSAU #1315 Move in and RU pull pump. ND wellhead. Clean out to TD at and underream openh	tion well. X uses (Clearly state all persistent details, a ing unit, reverse unit NU BOP. TOH w/tubir 3,936'. TOH w/bit. T 101e. TOH w/underreame	CASING TEST AND CE OTHER: R = 59 t. ND wellhead. NG. TIH w/bit, TH w/underreame	BOPNS. PLUG AND ABANDONMEN EMENT JOB ding estimated date of starting any proposed (TOH and lay down rods and drill collars and tubing. r, drill collars and tubing
PULL OR ALTER CASING DTHER: <u>Convert to inject</u> 12 Describe Proposed or Completed Cryster work) SEE RULE 1103 NMGSAU #1315 Move in and RU pull pump. ND wellhead. Clean out to TD at and underream openh openhole w/sonic/LD to TD. RU acid co. Solvent. TOH w/son	tion well. X tion well. X tions (Clearly rate all performent details, and NU BOP. TOH w/tubir 3,936'. TOH w/bit. T 101e. TOH w/underreame T/CNL/GR tools. RD Sc Acidize well w/5,000 ic hammer TIH w/tubi	CASING TEST AND CE OTHER: R = 59 M give pertinent dates, inclue R = 59 t. ND wellhead. ng. TIH w/bit, TH w/underreame er. RD air unit thlumberger. TI gals. 15% NEFE	TOH and lay down rods and drill collars and tubing. r, drill collars and tubing RU Schlumberger and log th H w/a sonic hammer on tubing HCL w/3% DP-77MX Micellar
PULL OR ALTER CASING DTHER: <u>Convert to inject</u> 12 Describe Proposed or Completed Crysta work) SEE RULE 1103. NMGSAU #1315 Move in and RU pull pump. ND wellhead. Clean out to TD at and underream openh openhole w/sonic/LD to TD. RU acid co. Solvent. TOH w/son Swab/flow back load and TIH w/2-3/8" 1j	tion well. X Xioos (Clearly rate all periverse unit NU BOP. TOH w/tubir 3,936'. TOH w/bit. T tole. TOH w/underreame T/CNL/GR tools. RD Sc Acidize well w/5,000 ic hammer. TIH w/tubi . TOH w/tubing and pa	CASING TEST AND CE OTHER: A give pertinent dates, inclus R = 959 T. ND wellhead. ng. TIH w/bit, IH w/underreame er. RD air unit chlumberger. TII gals. 15% NEFE ng and packer. cker, laying dow	TOH and lay down rods and drill collars and tubing. r, drill collars and tubing . RU Schlumberger and log tl H w/a sonic hammer on tubing HCL w/3% DP-77MX Micellar Set packer at ±3,700'. wn production tubing. Pick u
PULL OR ALTER CASING DTHER: <u>Convert to inject</u> 12 Describe Proposed or Completed Crysta work) SEE RULE 1103. NMGSAU #1315 Move in and RU pull pump. ND wellhead. Clean out to TD at and underream openh openhole w/sonic/LD to TD. RU acid co. Solvent. TOH w/son Swab/flow back load and TIH w/2-3/8" 1j	tion well. Woos (Clearly state all persistent details, all NU BOP. TOH w/tubir 3,936'. TOH w/bit. T 101e. TOH w/underreame NT/CNL/GR tools. RD Sc Acidize well w/5,000 ic hammer. TIH w/tubi . TOH w/tubing and pa ned injection tubing w	CASING TEST AND CE OTHER: A give pertinent dates, inclus R = 959 T. ND wellhead. ng. TIH w/bit, IH w/underreame er. RD air unit chlumberger. TII gals. 15% NEFE ng and packer. cker, laying dow	TOH and lay down rods and drill collars and tubing. r, drill collars and tubing . RU Schlumberger and log tl H w/a sonic hammer on tubing HCL w/3% DP-77MX Micellar Set packer at ±3,700'. wn production tubing. Pick u
PULL OR ALTER CASING DTHER: <u>Convert to inject</u> 12 Describe Proposed or Completed Crysta work) SEE RULE 1103. NMGSAU #1315 Move in and RU pull pump. ND wellhead. Clean out to TD at and underream openh openhole w/sonic/LD to TD. RU acid co. Solvent. TOH w/son Swab/flow back load and TIH w/2-3/8" li assembly. RD and m	tion well. X Xious (Clearly rate all periverse unit NU BOP. TOH w/tubir 3,936'. TOH w/bit. T tole. TOH w/underreame T/CNL/GR tools. RD Sc Acidize well w/5,000 ic hammer. TIH w/tubi . TOH w/tubing and pa ned injection tubing w ove out pulling unit.	CASING TEST AND CE OTHER: A give pertinent dates, inclus R = 959 T. ND wellhead. B TIH w/bit, TH w/underreame er. RD air unit chlumberger. TII gals. 15% NEFE ng and packer. cker, laying dow /injection packer Clean and clean	TOH and lay down rods and drill collars and tubing. r, drill collars and tubing . RU Schlumberger and log tl H w/a sonic hammer on tubing HCL w/3% DP-77MX Micellar Set packer at ±3,700'. wn production tubing. Pick u
PULL OR ALTER CASING DTHER: <u>Convert to inject</u> 12 Describe Proposed or Completed Crysta work) SEE RULE 1103. NMGSAU #1315 Move in and RU pull pump. ND wellhead. Clean out to TD at and underream openh openhole w/sonic/LD to TD. RU acid co. Solvent. TOH w/son Swab/flow back load and TIH w/2-3/8" 1j	tion well. X Xicos (Clearly rate all periverse details, all NU BOP. TOH w/tubir 3,936'. TOH w/bit. T tole. TOH w/underreame T/CNL/GR tools. RD Sc Acidize well w/5,000 ic hammer. TIH w/tubi . TOH w/tubing and pa ned injection tubing w ove out pulling unit.	CASING TEST AND CE OTHER:	TOH and lay down rods and drill collars and tubing. r, drill collars and tubing RU Schlumberger and log th H w/a sonic hammer on tubing HCL w/3% DP-77MX Micellar Set packer at ±3,700'. wn production tubing. Pick u er. ND BOP. NU wellhead r location.
DULL OR ALTER CASING DTHER: <u>Convert to inject</u> 12 Describe Proposed or Completed Crysta work) SEE RULE 1103. NMGSAU #1315 Move in and RU pull pump. ND wellhead. Clean out to TD at and underream openh openhole w/sonic/LD to TD. RU acid co. Solvent. TOH w/son Swab/flow back load and TIH w/2-3/8" li assembly. RD and m	tion well. X Xicos (Clearly rate all periverse details, all NU BOP. TOH w/tubir 3,936'. TOH w/bit. T tole. TOH w/underreame T/CNL/GR tools. RD Sc Acidize well w/5,000 ic hammer. TIH w/tubi . TOH w/tubing and pa ned injection tubing w ove out pulling unit.	CASING TEST AND CE OTHER:	BOPNS. PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed (TOH and lay down rods and drill collars and tubing. r, drill collars and tubing r, drill collars and tubing r, drill collars and tubing H w/a sonic hammer on tubing HCL w/3% DP-77MX Micellar Set packer at ±3,700'. wn production tubing. Pick u er. ND BOP. NU wellhead- r location. Sistant03-22-95
PULL OR ALTER CASING DTHER: Convert to inject 12 Describe Proposed or Completed Operative Work) SEE RULE 1103. NMGSAU #1315 Move in and RU pull pump. ND wellhead. Clean out to TD at and underream openh openhole w/sonic/LD to TD. RU acid co. Solvent. TOH w/son Swab/flow back load and TIH w/2-3/8" li assembly. RD and m Ibereby cereby that the information shore is the SNNATURE TYPE OR PROVINANCE (This space for State Use) ORIGINAL	tion well. Woos (Clearly state all persistent details, all NU BOP. TOH w/tubir 3,936'. TOH w/bit. T tole. TOH w/underreame T/CNL/GR tools. RD Sc Acidize well w/5,000 ic hammer. TIH w/tubi . TOH w/tubing and pa ned injection tubing w ove out pulling unit.	CASING TEST AND CE OTHER:	TOH and lay down rods and drill collars and tubing. r, drill collars and tubing RU Schlumberger and log th H w/a sonic hammer on tubing HCL w/3% DP-77MX Micellar Set packer at ±3,700'. wn production tubing. Pick u er. ND BOP. NU wellhead r location.

¹ Submit 3 Copies to Appropriate Distinct Office	State of New Me E Ty, Minerals and Natural Re		Form C-103 Revised 1-1-89		
D <u>ISTRICT 1</u> P.O. Bax 1980, Habbs, NM 88240	OIL CONSERVATIO		WELL API NO.		
DISTRICT II P.O. Drawer DD, Artesia, NM 8821:)	P.O. Box 20 Santa Fe, New Mexico		3002504126 5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			STATE FEE X		
			6. State Oil & Gas Lease No.		
(DO NOT USE THIS FORM FOR PR DIFFERENT FIESE (FORM C	ICES AND REPORTS ON WE IOPOSALS TO DAILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PE C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name		
I. Type of Well: OL QAS WELL X WELL			NORTH MONUMENT G/SA UNIT BLK. 13		
2. Name of Operator AMERADA HESS CORPURAT	TION		8. Well No. 15		
3. Address of Operator	, MONUMENT, NEW MEXICO	88265	9. Pool same or Wildcat		
4. Well Location			EUNICE MONUMENT G/SA		
Unit Letter ;61	60 Feet From The SOUTH	Line and1	980 Feet From The <u>EAST</u> Line		
Section 35	Township 19S R	ange 36E	NMPM LEA County		
II. Check NOTICE OF IN	Appropriate Box to Indicate		Report, or Other Data BSEQUENT REPORT OF:		
		REMEDIAL WORK			
	CHANGE PLANS	COMMENCE DRILLIN			
		CASING TEST AND C			
OTHER:		OTHER: REPLACE	CASING.		
12. Describe Proposed or Completed Ope work) SEE RULE 1103. NMGSAU #1315	rations (Clearly state all pertinent details,	and give pertinent dates, inci	luding estimated date of starting any proposed		
<pre>(06-23-93 Thru 06-28-93) DA&S Well Service moved in and rigged up pulling unit. TOH with a 1-1/4" x 16' polished rod with a 1-1/2" x 6' liner, 2 3/4" x 6' pony rods, 153-3/4" sucker rods and a 2-1/2" x 1-1/2" x 12' pump with a 1" x 6' gas anchor. Found majority of gas anchor perfora- tions plugged with debris and several 3/4" sucker rods coated with scale. Pumped 10 bbls. fresh water down casing-tubing annulus, removed 8-5/8" National Type "E" tubing- head slip assembly and installed an 8-5/8" Larkin adapter flange and a 6" 900 manual BOP. TOH with 124 jts. 2-7/8" 8rd EUE tbg., 2-7/8" SN, 2-7/8" perforated tbg. sub and 1 jt. 1-7/8" tbg., bull plugged as mud anchor. Note: mud anchor had a large amount of possible Barium Sulfate scale on exterior of jt. TIH with a 6-1/4" drill bit, bit sub and 125 jts. 2-7/8" tbg. Tagged at 3,900' for 36' of fill in openhole. TOH w125 jts. (Continued On Back)</pre>					
I hereby certify that the information above is	I W		Assistant05-03-94		
TYPE OR PRINT NAME	Terry L. Harvey		TELEPHONE NO. 393-2144		
(This space for State Use)		ORIGINAL BOLTO Devia a casa	T ATT A BENTON		
APPROVED BY		TTLE	DATE		
CONDITIONS OF APPROVAL, P ANY:					

NMGSAU #1315 (Pa 2)

(06-23-93 Thru 06-28-93 Continued) 2-7/8" tbg., bit sub and drill bit. TIH with a 7" Elder Lok-Set retrievable bridge plug, retrieving tool and SN on 120 jts. 2-7/8" tbg. Set RBP at 3,720', circ. casing with 140 bbls. fresh water and pressure tested the casing from 0' to 3,720'. Checked surface intermediate casing annulus and found no press. or flow. Checked intermediate-production casing annulus and found 20 psi and gas flow for 20 seconds. Pumped 1.92 BPM at 200 psi into casing leak and press. increased to 600 psi. Shut down pump and press. decreased to 0 psi in 1 min. TOH with 119 jts. 2-7/8" tbg., SN and retrieving tool. TIH with a 7" Elder Fullbore packer and SN on 39 jts. 2-7/8" tbg. Press. tested casing from O' to 1,232' and press. decreased from 330 psi to 0 psi in 1 min. Re-set packer repeatedly and located casing leak from 231' to 262'. Circulated through casing leak from 231' to 262' and out intermediate-production casing annulus. Press. tested casing from 262' to 3,720' and press. remained at 540 psi for 30 mins. Released packer at 262' and TOH with 8 jts. 2-7/8" tbg., SN and packer. TIH with retrieving tool and SN on 120 jts. 2-7/8" tbg., released RBP at 3,720' and TOH w/120 jts. 2-7/8" tbg., sn, retrieving tool and 7" RBP. TIH with a 2-7/8" perforated tbg. sub, bull plugged, 2-7/8" SN and 124 jts. 2-7/8" tbg. Removed 6" 900 manual BOP and 8-5/8" Larkin adapter and installed an 8-5/8" National Type "E" tubinghead slip assembly. Set bottom of tubing at 3,878'. TIH with 153-3/4" sucker rods, 2 3/4" x 6' pony rods and a 1-1/4" x 16' polished rod with a 1-1/2" x 6' liner. Cleaned location and rigged down pulling unit. Note: Well failed the NMGSAU casing integrity test.

(04-05-94 Thru 04-12-94)

DA&S moved in and rigged up pulling unit and TOH w/153-3/4" sucker rods, 2 3/4" x 6' pony rods, and a 1-1/4" x 16' polish rod w/1-1/2" x 6' polish rod liner. Removed wellhead and installed 6" 900 BOP. TIH and tag top of fill at 3,902' for a total of 34' of fill in open hole. TOH w/125 jts. of 2-7/8" tubing. TIH w/7" RBP and 118 jts. of 2-7/8" tubing and set at 3,688'. Circulate casing clean. Dump 3 sacks of sand on RBP. TOH w/7" fullbore packer and 8 jts. of 2-7/8" tubing to 264'. Test RBP to 500 psi. Held OK. Pulled up 1 jt. to 226'. Tested from 226' to surface to 500 psi. Held OK. Pumped 160 bbls. fresh water to circulate casing clean. Circulated to surface through 9-5/8" int. and 13" surface casing. Removed BOP. Removed 7" tubinghead. Ran a spear with a 24# grapple on a lift sub and picked up on the 7" casing w/84,000# of tension. Removed old wellhead and installed a new one. Installed 10" 900 BOP. Rigged up Schlumberger and ran PAL log. Found bad casing from 430' to surface. Rig up Jarrel Service and TIH w/freepoint. Found 7" casing free at 500'. Attempted to find top of cement w/freepoint but tool malfunctioned. TOH and rigged up 200 GR shot. Attempted to back off at 496' but backed off at 7" lift sub. Removed BOP and welded lift sub back into casing collar. Installed casing head and BOP Rigged up w/200 GR shot and backed off of casing at 498'. TOH w/16 jts. of 71 24# short thread 10V casing. TIH w/changeover pup joint w/screw-in-tipland 12 jts. of 7" 20# casing. Screwed casing back and made up w/2,540 lbs. of torque. Installed 7" wellhead, set casing on the slips w/84,000# of tension and cut off 7" casing at

DCL.

(Continued on Page 3)

NMGSAU #1315 Tage 3)

(04-05-94 Thru 04-12-94 Continued) wellhead. Installed 6" 900 BOP. Performed NMGSAU casing integrity test to 540 psi. Pressure decreased to 500 psi in 31 minutes. Note: Well passed the NMGSAU casing integrity test and bradenhead test. TIH w/retrieving tool and 118 jts. of 2-7/8" tubing. Circulate sand off of RBP. Latched onto RBP and TOH w/tubing and RBP. TIH w/6-1/4" bit, bit sub, and 125 jts. of 2-7/8" tubing. Tagged top of fill at 3,902' and broke circulation w/140 bbls. fresh water. Cleaned out fill to 3,936'. Circulate OH clean. TOH w/tubing and bit. TIH w/2-3/8" SN, 2-7/8" Salta lined tubing, 5 jts. of 2-7/8" tbg., a 7" x 2-7/8" TAC, and 119 jts. of 2-7/8" tubing. Set SN OE at 3,908'. Set TAC at 3,717' w/14,000# of tension. Removed wellhead and installed BOP. TIH w/2" x 1-1/4" RHBC 8' x 3' x S x 4' sucker rod pump #A-1168 on 154-3/4" rods, 3 3/4" x 8' pony rods, 1 3/4" x 2' pony rod and a 1-1/4" x 16' polish rod w/1-1/2" x 6' polish rod liner. Rod boxes and pin threads chased and lubricated w/corrosion inhibitor and oil and made up w/rod tongs. Rigged down pulling unit, cleaned and cleared location. Installed wellhead and resumed prod. well.

Test (24 Hours) 04-26-94: 9 BOPD, 23 BWPD, and 8 MCFGPD

