

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name State "H"
3. Address of Operator Drawer D, Monument, New Mexico 88265	9. Well No. 2
4. Location of Well UNIT LETTER <u>J</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>1</u> TOWNSHIP <u>20S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat Eunice-Monument G/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3562' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <u>Casing leak squeeze.</u> <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU pulling unit & TOH w/rods & pump. Install BOP & TOH w/tbg. TIH w/6-5/8" RBP & Md. R. dbl. grip pkr. Set RBP above perms. & test to 1000#. Test tbg. to 1000#. Locate csg. leak & establish inj. rate into leak. Spot sand on top of RBP & TOH. TIH w/cement retainer. Load & press. backside to 500# & tbg. to 3000#. Squeeze leak w/+ 300 sks. Class C Neat cement. WOC. Drill out cement & test squeeze to 500#. Wash sand off RBP & pull plug. TIH w/prod. eqpt. & resume producing well.

THE COMMISSION MUST BE NOTIFIED  
24 HOURS PRIOR TO ANY PLUG WORK

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Denise Ward TITLE Senior Petroleum Engineer DATE 6-3-88

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT ENGINEER

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: