

EMSUB # 913

PROCEDURE TO PLUG AND ABANDON

Notify OCD/BLM 24 hrs prior to operations.

1. MIRU PU. NU BOP.
2. TIH w/5-1/2" CIBP. Set CIBP @ 3716 +/-.
3. RU BJ. Cap CIBP w/25 sack Class 'C' from 3716' to 3470'.
4. Pump 19 bbl 9# mud, from 3470' TO 2655'.
5. Spot 25 sacks Class 'C' cmt from 2655' to 2405'. (bottom of Salt @ 2530')
6. PUH & pump 26 bbl 9# mud.
7. Spot 100' (or 25 sks) Class 'C' cmt plug from 1028' to 1278'. - *Tag*
Top of Salt @ 1215'.
8. PUH and pump 18 bbls 9# mud.
9. Spot 25 sacks Class 'C' cmt from 250' to surface. RD BJ. WOC.
10. ND BOP. RD PU.
11. ND WELLHEAD. Cut off casing 4' below GL & cap.
12. Install 4" maker 4' above GL w/ the following stamped in it:
Chevron U.S.A. Production Company
EMSUB # 913
1980' FSL & 990' FWL
T-20S, R-36-E, Sec 24, Unit L
Lea County, NM
13. Remove all equipment, deadman, and junk from location.
14. Fill any pits and level location.

(Note: 9# mud to contain 0.6 # of gel / gal.)

T. Love 687-7645