

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Chevron U.S.A. Inc.

Address of Operator

P.O. Box 670 Hobbs, NM 88240

Location of Well

UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM
THE West LINE, SECTION 36 TOWNSHIP 20S RANGE 36E NMPM.

7. Unit Agreement Name

Eunice Monument S. U

8. Farm or Lease Name

9. Well No.

166

10. Field and Pool, or Wildcat

Eunice Monument G/SA

15. Elevation (Show whether DF, RT, GR, etc.)

3562

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐

PORABLY ABANDON ☐

OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER Dpn, log, acdz ☒

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

TD: 4037 PB: 3993

Work performed 5-15-88 thru 5-29-88

POOH w/production equipment. Break circ., circ. clean. Set pkr at 3615'. Test RBP to 500psi, ok., test csg to 500psi, ok. Cleanout hydromite plug from 3817'-50'. Drilled 150' new hole f/3850' to 4000'. Circulate clean. Drld f/4000 to 4037, circ. clean. Log w/GR, CNL, CCL & Cal. RIH w/4" liner, 12.93#, K-55, on 2 3/8" WS. Set on bottom at 4037. TOL at 3413. Pmp 2x tbq/liner cap. Batch mix 100sx Cl C cmt. Displace w/FW, WOC 16 hrs. DO 412' cmt. DO FC and hard cmt f/3975 to 4035, circ hole clean. Test liner to 500psi, ok. Log w/ CBL-GR. RIH w/ 2 1/8" perf guns. Perf zone 3 w/22 shots (4000' to 4022') 1 SPF, 180° phase. Spot 100 gallons acid across perf interval. Acdz perf interval 4000-4022 w/1000 gal 15% NEFE. Swab. Pmp FW through stinger. Sting into CICR. Load csg w/ FW, press to 500psi, Establish rate down tbq w/ FW, pmp 86 sx Class C cmt. Stung out of CICR. Reverse out 15.3bbbls cmt. Put 20sx into form. Perf 4" liner w/1 SPF, 180° phased at 3906'-24, 3928'-40, 3954'-66, 3978-88 in 2 runs. Spot 100 gallons 15% NEFE HCL across perfs. Pmpd 1300 gallons 15% NEFE HCL w/RCNBs in 1st 1000 gals acid. Swab. TIH w/ 2 3/8" prod. tbq, to 3989', SN at 3957. RIH w/ prod. equip. Load tbq w/CKF, tst to 500psi, ok. ck pump action-ok. Turn over to

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

production.

M. E. Abbin

TITLE: Staff Drilling Engr.

DATE: June 8, 1988

ORIGINAL SIGNED BY SUNDY SECTION

ED BY
ITIONS OF APPROVAL, IF ANY:

TITLE

DATE