

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☒ GAS ☐ OTHER ☐ 2. Name of Operator Chevron U.S.A. Inc. 3. Address of Operator P.O. Box 670, Hobbs, NM 88240 4. Location of well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>20S</u> RANGE <u>36E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3560	7. Unit Agreement Name Eunice Monument Sou 8. Farm or Lease Name Unit 9. Well No. 141 10. Field and Pool, or Wildcat Eunice Monument G/SA 12. County Lea
---	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER <u>dpr, log, acdz</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed: 6-1-88 thru 6-14-88 TD: 4015

POOH w/production equipment. Drill new hole f/3849 to 4015'. Circ hole clean. Log w/ GR-CCL, CNL, CDL-Calp. RIH w/ 4" liner to 4015', FC at 3982', TOL at 3420'. Pmp 100sx C1 C, displ w/ FW, WOC 24 hrs. Drill out cmt stringer to TOL at 3420, test to 500psi, ok. Cont. drilling out cement to 4015. Test liner to 500psi, ok. Run GR/CCL/CBL. Perf Zone 3 3980-4008 w/28 holes, 1 SPF, 180° phase, spot 100 gallons NEFE across perf interval. Acdz Zone 3 w/ 1500 gallons NEFE, Swab. Set CIBP at 3970'. Perf zone 2 w/ 1 SPF, 180° phase, 38 holes at 3910-24, 3931-47, 3952-60. Spot 100 gallons acid across perfs 3910-60. Pump 1800 gallons acid dropping 4 1.1 ball sealers every 100 gallons for 1st 1400 gallons. Perf Zone 1 3861-67, 3870-84, 3888-98, 30 holes total, Set CIBP at 3905', spot 50 gallons 15% NEFE HCL across perfs Zone 1. pump 1450 gallons acid dropping 9 1.1 balls every 200 gallons thru 1st 1000 gallons, Swab. Drill out CIBP's at 3905, 3970 & 3970. Run 2 3/8" tbq to 3997'. TAC at 3263', run rods and pump. space out hang off, tst to 500psi, ok. Turn over to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Drlg. Tech. Asst. DATE July 1, 1988

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: