NO. OF COPIES RECEIVED					Form C-10	5
DISTRIBUTION					Supersedes	
SANTA FE		NEW MEXICO	OIL CONSERVAT	ION COMMISSION	C-102 and	
FILE			JIL CONSERVAL	TOIR COMMISSION	Effective]	-1-65
U.S.G.S.		3-NMOCC			5a. Indicate T	rne of Legge
LAND OFFICE		1-FILE			State ¥	Fee
OPERATOR		1-contine	ENTAL OIL COM	PANY - HOBBS	44	Gas Lease No.
	لــــــــــــــــــــــــــــــــــــــ				o, state on a	Gds Ledse No.
	SUNDRY NO	TICES AND REF	PORTS ON WELL	S	mill	
(DO NOT USE THIS FOR	APPLICATION FO	TO DRILL OR TO DEER PERMIT -" (FORM C	PEN OR PLUG BACK TO A -101) FOR SUCH PROPO	S DIFFERENT RESERVOIR. SALS.)		
OIL GAS					7. Unit Agreen	nent Name
WELL WELL Name of Operator	01	HER.		·		
					8. Form or Lea	
GRITY OIL COMPAN 3. Address of Operator	IX				9. Well No.	ONT UNIT
P. O. BOX 249, 1	OBBS. NEW	MEXICO 88240)		74	
Location of Well		121200 0021				Pool, or Wildcat
UNIT LETTER	1980	FFFT FROM THE	SOUTH	1980	EUMONTE OF	·
		TECT FROM THE	LINE	ANDFEE	T FROM	
THE EAST	NE, SECTION	27 TOWNSH	IP 19-S	ANGE 37-E	NMPM.	

		15. Elevation (S	how whether DF, RT,	GR, etc.)	12. County	
<u> </u>	71111111	7/	3624 RT		LEA	
10.	Check Appro	priate Box To I	Indicate Nature	of Notice, Report o	or Other Data	
NOTIC	E OF INTEN	TION TO:	1		UENT REPORT OF	=:
السا				-	_	
PERFORM REMEDIAL WORK		PLUG AND A	BANDON BEMED	AL WORK	ALT	ERING CASING
===		. 200 ARD A	The Later Later Remains	<u> </u>		
TEMPORARILY ABANDON		1 200 AND A	<u> </u>	NCE DRILLING OPNS.	PLUC	AND ABANDONMENT
TEMPORARILY ABANDON		CHANGE PLA	COMME		PLUC	S AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING			COMME	NCE DRILLING OPNS.	PLUC	AND ABANDONMENT
TEMPORARILY ABANDON			COMME	NCE DRILLING OPNS. TEST AND CEMENT JQB	PLU	S AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Con work) SEE RULE 1103.		CHANGE PLA	COMME CASING OTH pertinent details, and	NCE DRILLING OPNS. TEST AND CEMENT JQB ER give pertinent dates, inc	luding estimated date o	f starting any proposed
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Con	forated 5 and 20,6 blocking Treated t good trea pulled. 1	change PLA Is (Clearly state all) -1/2" casing 000# 20-40 sa agent. Fina with 1,000 ga atment from 3	orh archiver details, and 3757 to 3816 and; 1,000 g al log indicates 15% NE ac 3760' to 3816 con pump.	rest and cement JQB give pertinent dates, inc selectively wals. 15% NE aci ted treated old cid, 20,000 gal and minor tre	luding estimated date of the 19 jets. d and 200# ber perforations s. and 20,000# eatment 3757-58	Treated azoic acid BP set @ 3824' 20-40 sand. 3'. Washed
PULL OR ALTER CASING OTHER 7. Describe Proposed or Conwork) SEE RULE 1103. Additionally perwith 20,000 gals and 200# salt as packer @ 3698'. Final log showed sand off BP and Well was pumping and 108 BLW, in	forated 5. and 20,6 blocking Treated to good treated pulled. 1 35 BO and 24 hours.	change PLA Is (Clearly state all -1/2" casing 000 20-40 sa agent. Fina with 1,000 ga thent from 3 Put well back 1 6 BWPD price 1 CNED BY: Wode	pertinent details, and 3757 to 3816 and; 1,000 gal log indicates. 15% NE action pump. To to workove:	r. Production a	with 19 jets. d and 200# ber perforations s. and 20,000 atment 3757-58	Treated azoic acid BP set @ 3824' 20-40 sand. 3'. Washed tested 59 BO
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Conwork) SEE RULE 1903. Additionally perwith 20,000 gals and 200# salt as packer @ 3698'. Final log showed sand off BP and Well was pumping and 108 BLW, in	forated 5. and 20,0 blocking Treated 1 good tree pulled. 1 35 BO and 24 hours.	change PLA is (Clearly state all) -1/2" casing 000 20-40 sa agent. Fina vith 1,000 ga Atment from 3 Put well back 1 6 BWPD price 1 CMED BY: Wade	pertinent details, and 3757 to 3816 and; 1,000 gal log indicates. 15% NE action pump. er to workove:	r. Production a	with 19 jets. d and 200# ber perforations s. and 20,000 atment 3757-58	Treated azoic acid BP set @ 3824' 20-40 sand. 3'. Washed
PULL OR ALTER CASING OTHER 7. Describe Proposed or Conwork) SEE RULE 1103. Additionally perwith 20,000 gals and 200# salt as packer @ 3698'. Final log showed sand off BP and Well was pumping and 108 BLW, in	forated 5. and 20,0 blocking Treated 1 good tree pulled. 1 35 BO and 24 hours.	change PLA is (Clearly state all) -1/2" casing 000# 20-40 sa agent. Fina with 1,000 ga attent from 3 Put well back 1 6 BWPD price I CNED BY: Wade	pertinent details, and 3757 to 3816 and; 1,000 gal log indicates. 15% NE action pump. To to workove:	r. Production a	with 19 jets. d and 200# ber perforations s. and 20,000 atment 3757-58	Treated azoic acid BP set @ 3824' 20-40 sand. 3'. Washed tested 59 BO
PULL OR ALTER CASING OTHER 7. Describe Proposed or Conwork) SEE RULE 1103. Additionally perwith 20,000 gals and 200# salt as packer @ 3698'. Final log showed sand off BP and Well was pumping and 108 BLW, in	forated 5. and 20,0 blocking Treated 1 good tree pulled. 1 35 BO and 24 hours.	change PLA is (Clearly state all) -1/2" casing 000# 20-40 sa agent. Fina with 1,000 ga attent from 3 Put well back 1 6 BWPD price I CNED BY: Wade	pertinent details, and 3757 to 3816 and; 1,000 gal log indicates. 15% NE action pump. To to workove:	r. Production a	with 19 jets. d and 200# ber perforations s. and 20,000 atment 3757-58	Treated azoic acid BP set @ 3824' 20-40 sand. 3'. Washed tested 59 BO