Attachment - C-103

Gulf Oil Corporation - B. V. Culp "B" No. 3-9, 31-19-37

Repaired 5-1/2" casing leak as fellows:

1. Pulled tubing.

2. Ran 5-1/2" Baker Model N bridge plug set at 3730'. Dumped 2 wacks cement on top of plug.

3. Ran HRC tool. Found leak between 510' and 540'.

4. Perforated 5-1/2" easing with 2 Jet Holes at 1115'.

5. Ran 5-1/2" Howeo IM coment retainer set at 1060'. Pumped 120 sacks 4% Gel coment below retainer and circulated out 7-5/8" casing. Closed 7-5/8" bradenhead and squeezed with 200%. Picked tubing up 10' and reversed out approximately 20 sacks coment.

6. Waited on cement.

7. Pressured 10-3/4" easing with 200# for 30 minutes. No drop in pressure. Pressured 5-1/2" easing with 500# for 30 minutes. Moddrop in pressure. Pressured 7-5/8" easing with 300% for 30 minutes. No drop in pressure.

8. Drilled sement and retainer to 1156. Pressured 5-1/2" casing with 600#. Hed off 100# in 1-1/2 hours.

9. Ran HRC tool. Found leak between 1104 and 1135 and between 1505

and 1536'.

10/ Set 5-1/2" DM ecment retainer at 1061'. Squeezed 360 sacks 4% Gel cement below retainer. Pumped 250 sacks, staged 114 sacks in 4 stages. Maximum pressure 800%. Back washed 20 sacks cement.

11. Waited on coment.

12. Pressured 5-1/2" casing with 500#. No drep in pressure. Drilled cement and retainer to 1490'. Pressured 5-1/2" casing at 1151', 1244' and 1500' with 500%. He drop in pressure.

13. Drilled out bridge plug. Returned well to production.