## State of New Mexico Energy, Minerals and Natural Resources Department

P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 2088	30-025-05810
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DISTRICT III	STATE FEE XX
1000 Rio Brazos Rd., Aztoc, NM 87410	6. State Oil & Ges Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
L. Type of Well:	
OR WELL OTHER	JAMES H. WILLIAMS
ARCO OIL AND GAS COMPANY	8. Well No.
Address of Operator	9. Pool same or Wildcat
P. O. BOX 1710, HOBBS, NEW MEXICO 88240	EUNICE MONUMENT GRBG/SA
Well Location	
Unit Letter 0 : 330 Feet From The SOUTH Line and 2310	Feet From The EAST Line
Section 33 Township 19S Range 37E	MPM LEA . COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3568 GR	County
NOTICE OF A PROPERTY OF THE PROPERTY OF TABLE OF TABLE	
	SEQUENT REPORT OF:
THE DATE WORK	ALTERING CASING
THE WORK WORK	
THOOPAGE VARANCON V	OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLING COMMENCE DRILLI	OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLING COMMENCE DRILLI	OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLING COMMENCE DRILLI	OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLING COMMENCE DRILLI	OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLING COMMENCE DRILLI	OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLING CASING TEST AND CENTER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hrs PRIOR TO TESTING CIBP  2. MIRU	OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLING & CASING TEST AND CENTER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hrs PRIOR TO TESTING CIBP 2. MIRU 3. INSTALL BOP & GIH TO TAG PBTD	OPNS. PLUG AND ABANDONMENT
COMMENCE DRILLING COMMENCE DRI	OPNS. PLUG AND ABANDONMENT
COMMENCE DRILLING COMMENCE DRI	OPNS. PLUG AND ABANDONMENT
COMMENCE DRILLING CASING TEST AND CENTER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hrs PRIOR TO TESTING CIBP 2. MIRU 3. INSTALL BOP & GIH TO TAG PBTD 4. POH w/TBG, TOH 5. GIH w/TBG OR WL SET CIBP 6. SET CIBP MAXIMUM 50' ABOVE EXISTING PERFS	OPNS. PLUG AND ABANDONMENT ABOUT JOB
COMMENCE DRILLING CASING TEST AND CEM  CASING TEST AND CEM  CASING TEST AND CEM  OTHER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hrs PRIOR TO TESTING CIBP  2. MIRU  3. INSTALL BOP & GIH TO TAG PBTD  4. POH w/TBG, TOH  5. GIH w/TBG OR WL SET CIBP  6. SET CIBP MAXIMUM 50' ABOVE EXISTING PERFS  7. POH w/1 JT & CIRC A MIX OF 2 GAL WT675 CHEM PER 10 BBLS	OPNS. PLUG AND ABANDONMENT  MENT JOB  Gestimated date of starting any proposed  8.6# BRINE
CASING TEST AND CEN  CHANGE PLANS  CASING TEST AND CEN  OTHER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin  work) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hrs PRIOR TO TESTING CIBP  2. MIRU  3. INSTALL BOP & GIH TO TAG PBTD  4. POH w/TBG, TOH  5. GIH w/TBG OR WL SET CIBP  6. SET CIBP MAXIMUM 50 ABOVE EXISTING PERFS  7. POH w/1 JT & CIRC A MIX OF 2 GAL WT675 CHEM PER 10 BBLS  8. WHEN CIRC IS ESTABLISHED w/TREATED FLUID AT SURFACE, TES	OPNS. PLUG AND ABANDONMENT  MENT JOB  Gestimated date of starting any proposed  8.6# BRINE
CASING TEST AND CEN  CASING TEST AND CEN  CASING TEST AND CEN  OTHER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin  work) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hrs PRIOR TO TESTING CIBP  2. MIRU  3. INSTALL BOP & GIH TO TAG PBTD  4. POH w/TBG, TOH  5. GIH w/TBG OR WL SET CIBP  6. SET CIBP MAXIMUM 50' ABOVE EXISTING PERFS  7. POH w/1 JT & CIRC A MIX OF 2 GAL WT675 CHEM PER 10 BBLS  8. WHEN CIRC IS ESTABLISHED w/TREATED FLUID AT SURFACE, TESTING CUT CHART	OPNS. PLUG AND ABANDONMENT ABOUT JOB
CASING TEST AND CEN  CHANGE PLANS  CASING TEST AND CEN  OTHER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin  work) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hrs PRIOR TO TESTING CIBP  2. MIRU  3. INSTALL BOP & GIH TO TAG PBTD  4. POH w/TBG, TOH  5. GIH w/TBG OR WL SET CIBP  6. SET CIBP MAXIMUM 50' ABOVE EXISTING PERFS  7. POH w/1 JT & CIRC A MIX OF 2 GAL WT675 CHEM PER 10 BBLS  8. WHEN CIRC IS ESTABLISHED w/TREATED FLUID AT SURFACE, TES	OPNS. PLUG AND ABANDONMENT MENT JOB DE COMMENT DE COMME
COMMENCE DRILLING CASING TEST AND CEN  LL OR ALTER CASING  MER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hRS PRIOR TO TESTING CIBP  2. MIRU  3. INSTALL BOP & GIH TO TAG PBTD  4. POH w/TBG, TOH  5. GIH w/TBG OR WL SET CIBP  6. SET CIBP MAXIMUM 50' ABOVE EXISTING PERFS  7. POH w/1 JT & CIRC A MIX OF 2 GAL WT675 CHEM PER 10 BBLS  8. WHEN CIRC IS ESTABLISHED w/TREATED FLUID AT SURFACE, TESTING CUT CHART  9. POH, LAYING DOWN - LEAVE 1 JT HANGING ON BI BONNETT	OPNS. PLUG AND ABANDONMENT ABOUT JOB
COMMENCE DRILLING OF CASING TEST AND CENTRE T	OPNS. PLUG AND ABANDONMENT MENT JOB DE COMMENT DE COMME
CASING TEST AND CENTRER:  CHERT:  CASING TEST AND CENTRER:  CASING TES	PLUG AND ABANDONMENT  MENT JOB  Restinated date of starting any proposed  8.6# BRINE ST CIBP TO 500# AND
COMMENCE DRILLING C  LL OR ALTER CASING  HER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including voork) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hrs PRIOR TO TESTING CIBP 2. MIRU 3. INSTALL BOP & GIH TO TAG PBTD 4. POH w/TBG, TOH 5. GIH w/TBG OR WL SET CIBP 6. SET CIBP MAXIMUM 50' ABOVE EXISTING PERFS 7. POH w/1 JT & CIRC A MIX OF 2 GAL WT675 CHEM PER 10 BBLS 8. WHEN CIRC IS ESTABLISHED w/TREATED FLUID AT SURFACE, TESTING CUT CHART 9. POH, LAYING DOWN - LEAVE 1 JT HANGING ON BI BONNETT  THE Administrative Secretify that the information above is true and complete to the best of my knowledge and belief.  NATURE Administrative Secretify that the information above is true and complete to the best of my knowledge and belief.	PLUG AND ABANDONMENT  MENT JOB  Re estimated date of starting any proposed  8.6# BRINE ST CIBP TO 500# AND  Supervisor DATE 4/12/91
COMMENCE DRILLING CASING TEST AND CENTER:  CL Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.  TA & HOLD WELL BORE FOR SECONDARY RECOVERY  1. NOTIFY NMOCD 24 hRS PRIOR TO TESTING CIBP 2. MIRU 3. INSTALL BOP & GIH TO TAG PBTD 4. POH w/TBG, TOH 5. GIH w/TBG OR WL SET CIBP 6. SET CIBP MAXIMUM 50' ABOVE EXISTING PERFS 7. POH w/1 JT & CIRC A MIX OF 2 GAL WT675 CHEM PER 10 BBLS 8. WHEN CIRC IS ESTABLISHED w/TREATED FLUID AT SURFACE, TEST CUT CHART 9. POH, LAYING DOWN - LEAVE 1 JT HANGING ON BI BONNETT  COMMENCE DRILLING CASING CASING TEST AND CENTER TO THE SURFACE AND CENTER TO THE SURFACE AND COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CENTER TO THE SURFACE AND CENTER TO THE SURFACE AND COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CENTER TO THE SURFACE AND CENTER TO THE SURFACE AND COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CENTER THE SURFACE AND CENTER THE SURFACE AND COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CENTER THE SURFACE AND CENTER THE SURFACE AND CENTER THE SURFACE AND COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CENTER THE SURFACE AND CENTER THE SURFACE AND COMMENCE DRILLING CASING THE SURFACE AND COMMENCE DRILLING	PLUG AND ABANDONMENT  MENT JOB  Restinated date of starting any proposed  8.6# BRINE ST CIBP TO 500# AND