

**Bertha Barber Well No. 4**  
**NMOCD Form C-101**  
**Section 22, Page 2**

1. MIRU PU. POOH with tubing. RDMO PU.
2. MIRU Rod-Ric drilling rig.
3. NU BOPE and test.
4. RIH and spot LCM pill across Eumont perforations: 3200-3412' & 3555-3640'.
5. Establish circulation and drill 6-1/8" hole from PBTD to  $\pm 6800'$ .
6. Run openhole logs.
7. Run 4-1/2", 11.6 lb/ft, K-55, LT&C casing from surface to TD. Cement casing with 410 sxs. Estimated cement top to be at 3000' from surface.
8. RD Rod-Ric drilling rig.
9. MIRU CU. RIH w/ bit and casing scraper. Circulate hole. POOH.
10. Run GR-CBL-CCL. Perforate Tubb formation at  $\pm 6370'$  to 6630'. Perforations will be picked from open hole logs.
11. Acidize Tubb perforations for breakdown and sand fracture stimulate Tubb perforations.
12. Cleanout any fill and RIH with production tubing and packer.
13. RDMO CU.
14. Open well to sales.

