

**G. C. Matthews #1**  
**Section 6, T20S, R37E**  
**Lea County, New Mexico**  
**WBS UWPWB-A0017**

**Recommended P&A Procedure**

1. MIRU PU. Conduct Safety Meeting. Contact OCD. ND WH. NU BOP.
2. PU Tbg and TIH.
3. Place a 100' balanced cement plug from 3770' - 3670' (7" casing shoe). Tag plug.
4. Perf at 2367' with 4 hpf. Place a 100' balanced cement plug with 50' inside of casing and 50' outside of casing, 2367'-2267' (9 5/8" casing shoe). Tag plug.
5. Place a 100' balanced cement plug from 273' - 173' (13 3/8" casing shoe). Tag plug.
6. Place a 100' balanced cement plug from 100' - surface. (surface plug)
7. Cut off well head and set P&A marker.
8. RD PU. Cut off anchors. Change well status to P&A.
9. Restore surface location.

→ SALT PLUG 1175' - 1075'

Lloyd Trautman