

Page 2 of 2

BLM Form 3160-5 dated 5-03-01

Doyle Hartman

H.M. Britt No. 2

C-7-20S-37E

API No. 30-025-05990

In regard to the BLM's July 24, 2000 notice pertaining, in part, to non-producing wells on the 320-acre H. M. Britt lease (Sec. 7, T-20-S, R-37-E), as to the H.M. Britt No. 2 well, we hereby propose performing the following well operations.

1. Move in and rig up well service unit.
2. Run work string equipped with cementing stinger.
3. Sting into retainer setting at 3390'.
4. Establish pump-in rate.
5. Squeeze cement existing Grayburg perms, from 3453' - 3538'.
6. Drill out retainer and cement.
7. Rig up Schlumberger. Log well with VDCBL-GR-CCL log and DS-CNL-GR-CCL log.
8. If warranted (by results of logging job), run combination 5 1/2" O.D. x 5" O.D. casing string, to seal off the following squeeze perms, from 598' to 3538'.

<u>Squeeze Date</u>	<u>Depth</u>	<u>Holes</u>	<u>Cement Volume (sx)</u>	<u>Remarks</u>
6-24-77	3400	2	600	
6-25-77	2500	2	0	
6-25-77	950	2	850	
6-26-77	775	2	850	
6-28-77	598	2	450	
6-30-77	598	2	250	
3453-3538				Perforated 7-6-77
Total			2230 sx	

9. Cement 5 1/2" O.D. x 5" O.D. casing string back to surface.
10. Complete well, as Eumont producer, as replacement for adjacent H.M. Britt No. 12 Eumont well (C-7-20S-37E), which currently produces highly corrosive water, that has resulted in costly well operations; i.e., continual rod parts and tubing leaks.

RECEIVED  
2001 MAY -7 AM 10:18  
BUREAU OF LAND MANAGEMENT  
MONT. FIELD OFFICE

