

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on
reverse side)

Form approved
Budget Project No. 42-R1424
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different interval.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR UNION TEXAS PETROLEUM CORPORATION		8. FARM OR LEASE NAME Britt
3. ADDRESS OF OPERATOR 1300 Wilco Building, Midland, Texas 79701		9. WELL NO. 12
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND FOOT, OR WILDCAT Monument-Grayburg
11. PERMIT NO. 330' FNL & 2281' FWL		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 7, T-20-S, R-37-E
12. ELEVATIONS (Show whether DS, RT, OR, etc.) 3562' DF		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other) Plug Back & Recomplete		☒	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)		☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work).*

1. RU & re-enter well, install BOP and pull tubing & rods.
2. Set CIBP @ 3670' and dump 20' of cement on top.
3. Shoot 4 holes 3550' to 3551'. Set cement retainer @ 3500'. (Test casing above retainer to 2000#).
4. Establish circ. through 8 5/8" annulus and cement with 200 sx. Class "C". Pull out of retainer and dump 20' of cement above retainer.
5. Perforate Eumont Queen Zone.
6. Run tubing with packer & TD. Spot 1000 gal. acid across perfs.
7. Swab test.
8. Stimulate if necessary and swab test.
9. Kill well with Brine wtr. and pull tubing and packer.
10. Run tubing and swab well in.
11. Place well on production in the Eumont Queen Zone.

18. I hereby certify that the foregoing is true and correct

SIGNED *Stanley A. R...*
(This space for Federal or State Office use)

TITLE Gas Measurement Analyst

DATE 10-5-76

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

Bernard Moroz
BERNARD MOROZ
DISTRICT ENGINEER

*See Instructions on Reverse Side