	Form C-103 Supersedes Old
NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
	5a. Indicate Type of Lease
· )FFICE	State State Oil & Gas Lease No.
OR	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS TO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPLN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
WELL X WELL OTHER-	7. Unit Agreement Name
and of Operator	8. Form or Lease Name Bertha Barber
John H. Hendrix  Astress of Operator	9. Well No.
525 Midland Tower, Midland, Texas 79701	3
Location of Well  I. 2310 FEET FROM THE SOUTH 1990 FEET FROM	10. Field and Pool, or Wildcat  Eunice-Monument
UNIT LETTER L 2310 FEET FROM THE SOUTH LINE AND 990 FEET FRO	Editice-Hollanett
THE West LINE, SECTION 8 TOWNSHIP 20-S RANGE 37-E NMPN	
15. Elevation (Show whether DF, RT, GR, etc.) 3557 GR	12. County  Lea
Check Appropriate Box To Indicate Nature of Notice, Report or O	
•• •	T REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON COMMENCE CRIELING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB COMPLETE AS	a gas well 🔯
OTHER TO recomplete as a gas well x	
	g estimated date of starting any propose
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin work) SEE RULE 1103.  1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.	
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3	3573, 3585, 3593,
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.	3573, 3585, 3593,
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 36	3573, 3585, 3593, 3677, and 3680'.
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3	3573, 3585, 3593, 3677, and 3680'.
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3636, 36	3573, 3585, 3593, 3677, and 3680'.
<ol> <li>Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.</li> <li>Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3633, 3640, 3646, 3664, 3666, 3626.</li> <li>Run tubing and packer.</li> <li>Acidize with 5000 gallons 15% LSTNE acid. Test interval 3503.</li> </ol>	3573, 3585, 3593, 3677, and 3680'.
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3636, 36	3573, 3585, 3593, 3677, and 3680'.
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3636, 36	3573, 3585, 3593, 3677, and 3680'.
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3636, 36	3573, 3585, 3593, 3677, and 3680'.
<ol> <li>Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.</li> <li>Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3633, 3640, 3646, 3664, 3666, 3626</li> <li>Run tubing and packer.</li> <li>Acidize with 5000 gallons 15% LSTNE acid. Test interval 3503-5. Return well to producing status.</li> </ol>	3573, 3585, 3593, 3677, and 3680'.
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3633, 3640, 3646, 3664, 3666, 3646, 3666, 3646, 3666, 36	3573, 3585, 3593, 3677, and 3680'.
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3632, 3640, 3646, 3644, 3666, 36	3573, 3585, 3593, 3677, and 3680'.
1. Pull tubing and set CIBP @ 3690' w/2 sx. cement on top.  2. Perforate w/1-3/8" jet @ 3503, 3513, 3522, 3537, 3548, 3563, 3626, 3633, 3640, 3646, 3664, 3666, 3626, 3633, 3640, 3646, 3664, 3666, 3646, 3666, 3646, 3666, 36	3573, 3585, 3593, 3677, and 3680'.