

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-06042
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name L. Van Etten
2. Name of Operator Texaco Exploration and Production Inc.	8. Well No. 2
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	9. Pool name or Wildcat Eunice Monument GBSA
4. Well Location Unit Letter <u>M</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>9</u> Township <u>20S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3537' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) Notify OCD 24 hours prior to commencement of plugging operations.
- 2.) MIRUPU. Set CIBP @ 3650' and cap w/ 35' (6 sxs) cmt. (Class "C" w/ 2% CaCl<sub>2</sub>, 6.3 g/sack, 14.8 ppg, 1.32 ft<sup>3</sup>/sack). Load hole with mud.
- 3.) Run freepoint on 7" csg to determine TOC. Set 100' (17 sxs) cmt plug from 2315' to 2415'. TOH.
- 4.) TIH w/ wireline and shoot 2 squeeze holes @ 1180'. Circulate cmt. up 7"-9 5/8" annulus by pumping 400 sxs down 7" casing.
- 5.) Cut off wellhead. Install hole marker. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M.C. Duncan TITLE Engineer's Assistant DATE 7-12-91

TYPE OR PRINT NAME M.C. Duncan TELEPHONE NO. 393-7191

(This space for State Use) ORIGINAL FILED

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 16 1991

HOLDS OFFICE