STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT	A
OIL CONSERVATION DIVISI	ON .
DISTRIBUTION P. O. BOX 2088	For: C-103
SANTA FE, NEW MEXICO 8750	
rice	
U.S.O.S.	5a. Indicate Type of Lesse
LAND OFFICE	State Fre X
OPERATOR	5. State Oli 6 Gas Lease Lio.
SUNDRY NOTICES AND REPORTS ON WELLS	
DIL X GAB OTHER.	7. Unit Agreement Name
2. Name of Operator	8. Form or Lease Name
Amoco Production Company	
Address of Operator	South Hobbs (GSA) Unit
D. O. Poy 60 Habba New Marthe cooks	9. Well No.
P. O. Box 68, Hobbs, New Mexico 88240	57
	10. Field and Pool, or Wildcat
UNIT LETTER M. 205 FEET FROM THE South LINE AND 201	Hobbs GSA
THE West LINE. SECTION 3 TOWNSHIP 19-S RANGE 38	<u>-Еимем. ())))))))))))))))))))))))))))))))))))</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3602' GL	Lea
6. Check Appropriate Box To Indicate Nature of Notice, NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING O	PNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEM	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103.	dates, including estimated date of storting any proposed

Propose to plug and abandon well as follows:

Pull rods, pump, and tubing. Set a cement retainer at 4000'. Pump 100 sacks class C neat cement followed by 100 sacks class C with 4#/sack Tuff-plug. Tail in with 100 sacks class C neat. Cap cement retainer with 25 sacks class C neat. Spot 60 bbl 10# brine with 25# gel/bbl. Run freepoint on 8-1/4" casing string. Cut 8-1/4", 36# casing at 2700' if possible, and pull casing. Spot 65 sacks class C with 2% CaCl 2600'-2800'. Spot 100 bbl 10# brinewith 25# gel/bbl. Run freepoint on 10", 45# casing string. Cut 10" casing at 1500', if possible, and pull casing. Spot 95 sacks class C neat cement 1400'-1600'. Spot 108 bbl 10# brine with 25# gel/bbl. Cut 12-1/2" casing at 600' and pull casing. Spot 75 sacks class C neat cement 550'-650'. Spot 31 bbl 10# brine with 25# gel/bbl. Perforate 15-1/2", 70# casing 300'-301' with 4 JSPF. Establish circulation behind 15-1/2" casing string. Pump down 15-1/2" casing 350 sacks class C neat cement and circulate through 15-1/2" -20" annulus. Leave casing full to surface with cement. Weld on cap and erect PXA marker.

ORIGINAL SIGNED B	Y JERRY SEXTON	OCT 121987
PIENED Cathy Fr		t. Admin. Analyst 10-11-83
18. I hereby certify that the information of	shove is true and complete to the best of my	Anowlide BEN Petrel VeD
		HOUSE AND TO THE BROKING OF
0+5-NMOCD,H 1-HOU,	R. E. Ogden, Rm 21.150 1-	F. J. Nash HOU Rm 4.206 1-CLF