		بۇر
NO. OF COPIES RECEIVED		Form C-103
	1 Conservations C. C.	Supersedes Old
DISTRIBUTION SANTA FE NEW ME	HUPES THERE C. C. C. EXICO OIL CONSERVATION COMMISSION	<i>C-102 and C-103</i> Effective 1-1-65
FILE		
U.S.G.S.	JUL 7 2 37 PH '66	5a. Indicate Type of Lease
		State Fee 🗶
OPERATOR /		5. State Oll & Gas Lease No.
		Fee
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF (F USE "APPLICATION FOR PERMIT -" (F	D REPORTS ON WELLS TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
OIL CAS OTHER-	· · · · · · · · · · · · · · · · · · ·	7. Unit Agreement Name NONE
, Name of Operator		8, Farm or Lease Name
TEXACO Inc.		H. D. McKinley
Address of Operator P. 0. Box 72	28 - Hobbs, New Mexico	9. well No.
. Location of Well		10. Field and Pool, or Wildcat
P 330	M THE East 330 FEET FR	Hobbs
	TOWNSHIP 19-S RANGE 38-E NM	
· · · · ·		/////////////////////////////////
15, Eleve	ation (Show whether DF, RT, GR, etc.)	12. County
	3613' (D. F.)	Lea
Check Appropriate Box NOTICE OF INTENTION TO:	x To Indicate Nature of Notice, Report or SUBSEQUE	Other Data ENT REPORT OF:
		ALTERING CASING
PERFORM REMEDIAL WORK	IG AND ABANDON	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING CHA		
		······································
OTHER		
 Describe Proposed or Completed Operations (Clearly sta work) SEE RULE 1903. 	ate all pertinent details, and give pertinent dates, includ	ling estimated date of starting any proposed
The following Remedial Work has		
1. Pull rods & tubing, and sour	eeze perforations with 100 Sx. cem	nent at 3965! to 3985!.
	4290'. Run Gamma Ray-Neutron log	
4290' with 50 Sx. Class "C" Casing for 30 minutes with 3		iner, and test 5 1/2"
4. Perforate 2 7/8" Liner with	2 jet shots at 4247', 4255', 4264 tions with 50 Sx. Class "C" cement	Periorate 2 (/0"
Liner with 2 jet shots at 4 Acidize with 500 gals 15% M	148', 4160', 4180', 4184', 4188', E acid. Swab and flow well. Re-a well. Place well on pump to Test	cidize with 3000 gais
Liner with 2 jet shots at 4 Acidize with 500 gals 15% M 28% NE acid. Swab and flow	E acid. Swab and flow well. Re-a well. Place well on pump to Test ell Pumped 6 BBL Oil & 27 BBL Wate	
Liner with 2 jet shots at 4 Acidize with 500 gals 15% M 28% NE acid. Swab and flow 5. On 24 Hour Potential Test w 5, 1966. GOR - 333, GRAVIT	E acid. Swab and flow well. Re-a well. Place well on pump to Test ell Pumped 6 BBL Oil & 27 BBL Wate Y - 34.5.	
Liner with 2 jet shots at 4 Acidize with 500 gals 15% M 28% NE acid. Swab and flow 5. On 24 Hour Potential Test w 5, 1966. GOR - 333, GRAVIT	E acid. Swab and flow well. Re-a well. Place well on pump to Test ell Pumped 6 BBL Oil & 27 BBL Wate Y - 34.5. complete to the best of my knowledge and belief.	oldize with 3000 gais
Liner with 2 jet shots at 4 Acidize with 500 gals 15% N 28% NE acid. Swab and flow 5. On 24 Hour Potential Test w	E acid. Swab and flow well. Re-a well. Place well on pump to Test ell Pumped 6 BBL Oil & 27 BBL Wate Y - 34.5.	er ending 7:00 A. M. July
Liner with 2 jet shots at 4 Acidize with 500 gals 15% N 28% NE acid. Swab and flow 5. On 24 Hour Potential Test w 5, 1966. GOR - 333, GRAVIT 18. I hereby certify that the information above is true and c	E acid. Swab and flow well. Re-a well. Place well on pump to Test ell Pumped 6 BBL Oil & 27 BBL Wate Y - 34.5. complete to the best of my knowledge and belief.	er ending 7:00 A. M. July

CONDITIONS	OF	APPROVAL,	IF	ANY: