

NO. COPIES RECEIVED		
DISTRIBUTION		
OFFICE		
FOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. A-166	
7. Unit Agreement Name	
8. Farm or Lease Name O. O. Bradley	
9. Well No. 3	
10. Field and Pool, or Wildcat Bowers Seven Rivers	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Atlantic Richfield Company

3. Address of Operator

P. O. Box 1710, Hobbs, New Mexico 88240

4. Location of Well

UNIT LETTER B 330 FEET FROM THE North LINE AND 1650 FEET FROM
THE East LINE, SECTION 6 TOWNSHIP 19S RANGE 38E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3637' DF

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3277'. Presently completed OH interval 3238-3277' & perfs 3226-3236'.

8-5/8" OD 32# H-40 csg set @ 313' & cmtd w/250 sx.

5-1/2" OD 15.5# J-55 csg set @ 3238' & cmtd w/800 sx. No temp survey run.

This well is presently producing 2 BOPD, no gas and has depleted to uneconomical status. No other zones of interest. It is anticipated to be approx 5 to 10 years before a waterflood could be initiated. Propose to P&A in the following manner.

1. Rig up, install BOP & POH w/completion assy.

2. Pump cmt thru tbg from 3277-3200' OH & thru perfs 3226-3236' and 100' above top perforation inside 5 1/2" csg. Tag top of cmt.

3. Fill hole w/heavy gelled mud between all plugs.

4. Cut 5 1/2" OD csg as indicated from free pt & pull from approx 2030'.

5. Spot 100' cmt plug in & out of 5 1/2" csg stub @ 2030'.

6. Spot 100' cmt plug @ top of salt @ 1600'.

7. Spot 100' cmt plug in & out of 8-5/8" OD csg shoe.

8. Spot 10 sk cmt plug @ surface, erect regulation dry hole marker, clean & level location free of all junk.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED TITLE Dist. Drlg. Supv.DATE 5/28/75

APPROVED BY _____

TITLE _____

DATE JUN

CONDITIONS OF APPROVAL, IF ANY: