OIL CONSERVATION DIVISION Distribution SANTA FY FILE U.3.6.3. LAND OFFICE OFERAVOR	Farm C-103 Revised 19-1-7
	Sui Indicate Type of Louis State X Feo State Oli & Gus Louis No.
SUNDRY NOTICES AND REPORTS ON WELLS 100 HOT USE THIS FOR THE POPULATION TO POLICE OF TO POLICE AND REPORTS ON WELLS 1. 01. CAS WELL OTHER. Injection	7. Unit Agreement State
Amoco Production Company	d. Farm of Leave Lume South Hobbs (GSA) Un
P. O. Box 68, Hobbs, New Mexico 88240	9
WHIT LETTER G 1980 FEET FROM THE NORth LINE AND 1980	10. Field and Pool, or Mudat Hobbs GSA
THE East 19-5 38-E	
3602' DF	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or NOTICE OF INTENTION TO: SUBSEQUE	Other Data
PERPORM DEMEDIAL WORK X TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB	ALTERING CASING PLUC AND ABANGONMENT
OTHER	

Moved in service unit 4-2-83. Release packer, pulled tubing, packer and ran notched collar and tubing. Tagged at 4228'. Pulled tubing and tubing landed at 4098'. Spot sand, pulled tubing and tubing landed at 3790'. Ran tubing and tagged at 4171'. Pulled tubing and spot sand. Ran tubing and tagged at 4159'. Pulled tubing and notched collar. Ran dump bailer and wireline. Spot sand and pulled up dump bailer. Ran dump bailer, wireline and calseal. Unable to get past 2689'. Pulled up pump bailer and shut-in. Waited on weather. Ran tubing and cement retainer set at 3941'. Squeezed with 150 sacks class C cement, 50 sacks class C cement and 5# tuff plug. Max squeezing pressure 2500 PSI. Circulated out 8 sacks cement. Pulled tubing, setting tool and shut in overnight. Ran bit, drill collars, tubing and tagged at 3938'. Drilled out cement, cement retainer and cement to 4139'. Circulated, pulled tubing and shut in overnight. Finished pulling out of hole 2-3/8" tubing, 3-1/8" drill collars, 3-7/8" bit and 4-1/2" packer. Packer set at 3948' and pressure test squeeze to 1500 PSI. Bled down to O PSI in 4 min. Released packer, ran tubing with packer set at 4102'. Pressure test squeeze to 900 PSI and bled down to 0 PSI in 2 min. Released packer and pulled tubing with packer set at 3948'. Established injection rate 1/2 BPM at 2000 PSI. Shut-in overnight. Pulled tubing and packer. Ran cement retainer, tubing with retainer set at 3973'. Re-squeezed 4016'-4138' with 72 sacks class C neat cement. Air .8 BPM with max tubing pressure 2500 PSI and max squeezing pressure 2250 PSI. Reversed out 36 sacks, pulled tubing and setting 0+4-NMOCD,H 1-HOU R. E. Ogden RM 21.150 1-F. J. Nash, HOU RM 4.206 1-SUSP 1-PJS Indredy the Wins intormation above in true and complete to the best of my knowledge and belief. Assist. Admin. Analyst 6-14-83 ORIGINAL SIGNED BY JERRY SEXTON JUN 16 1983 DISTRICT I SUPPRIVISOR

OF APPROVAL, IF ANY

tool. 26 sack in formation. Ran 3-7/8" bit, drill could stand tubing. Drilled out dement, dement retainer and dement at 3970'-41**3**9'. Pulled tubing drill coll rs, bit and shut-in overnight. Ran packer and tubing with packer set at 3948. Pressure test perfs, 4016'-4138' to 1500 PSI and bled to 1000 PSI in 25 min, released packer and pull didu of hole. Ran 3-7/8 bit, drill collars and tubing. Drilled out calseal and leared at 4.39'-4261'. Pulled tubing drill collars and bit. Perf 4 SPF at 4034'-38',4041 -49. 4178 -76'. Ran packer, tubing and shut in overnight. Ran tubing and packer set at 4.6. Addide perfs 4166'-72' and open ed hole at 4178'-4261' with 4500 gal NE HCL. Pump 2 biols soft 300# ock salt and 100# 100 mesh salt in 300 gal gelled brine. Air 2.1 BFM and max obids pressure 1800 PSI, average trade tubing pressure 1000 PSI. Initial shut-in pressure vacuut. R leased packer: pulled tubing and packer. Ran production packer, tubing and dates set at 798'. Load dating and pressure test at 300 PSI and 0K. Move out service unit 4.13-83. Commencel injection at 9722 BW, tubing pressure 310 PSI, dasing pressure 0 in the hour. Inst 24 hours injected 1979 BW, tubing pressure 310 PSI, dasing pressure 0.

