

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5c. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - PXA	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY <i>(Stanford Oil Co.)</i>	8. Farm or Lease Name Wright
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 6
4. Location of Well UNIT LETTER L 2310 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 14 TOWNSHIP 19-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat Hobbs (GSA)
15. Elevation (Show whether DF, RT, GR, etc.) 3603.0	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER replug <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to replug (due to an NMOCD ruling) as follows:

Cut off cap and permanent abandonment marker to re-enter the well. Run in hole with workstring and bit for 15-1/2" 70# casing. Drill out cement and wooden plugs at 80' and 135'. Tag top of 10-3/4" casing cut point at 1050'. Circulate hole clean and pull out of hole. Run in hole with workstring. Spot 100 sx class C neat across the 8-5/8" casing cut point at 3181'. Tag top of plug. Spot 99 bbls of 10# brine with 25# gel per bbl. Spot 45 sx class C neat across the 10-3/4" casing shoe at 1672'. Tag top of plug. Spot 48 bbl of 10# brine with 25# gel/bbl. Spot 65 sx class C neat across the 10-3/4" casing cut point at 1050'. Tag top of plug. Spot 130 bbl of 10# brine with 25# gel/bbl. Spot 225 sx class C neat from 250' to surface. Weld on cap and erect a permanent abandonment marker.

O+5-NMOCD, H 1-R. E. Ogden, HOU Rm. 21.150 1-F. J. Nash, HOU Rm. 4.206 1-GCC

THE COMMISSIONER HAS ORDERED
24 HOURS PRIOR TO COMMENCING WORK

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Harry C. Clark* TITLE Assist. Admin. Analyst DATE 3-8-84

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE MAR 12 1984

CONDITIONS OF APPROVAL

O.K. R.A. Szelen

RECEIVED
MAR 9 1984
O.C.D.
HOBBS OFFICE