

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Foster "B"
8. Well No. 1
9. Pool name or Wildcat Nadine (Drinkard)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Bledsoe Petro Corp.
3. Address of Operator 3908 N. Peniel, Suite 500, Bethany, OK 73008	4. Well Location Unit Letter <u>O</u> : <u>1980</u> Feet From The <u>East</u> Line and <u>660</u> Feet From The <u>South</u> Line Section <u>14</u> Township <u>19-S</u> Range <u>38 E</u> NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3609 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods and pump. Circulate hole with 9.5 ppg (+) mud.
2. Pull bottom of tubing to 7266 ft. Spot cement from 7266 ft back to 7166ft
3. Pull bottom of tubing to 6725 ft. Spot cement from 6725 ft. back to 6625ft
4. Pull tubing string out of hole and lay down
5. Determine free point for 5 1/2 in. casing and back off.
6. Spot 100 ft. cement plug at back off point. *50' in & 50' out of Self*
7. Pull 5 1/2 in. casing to 1725 ft and spot cement from 1725 ft. back to 1625 ft.
8. Pull 5 1/2 in. casing to 100 ft. and spot cement from 100 ft. back to surface.
9. Weld steel plate on surface casing and install 4 ft (+) steel marker with name, number, and location engraved onto marker. Restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J.D. Rawdon TITLE Operations Manager DATE 11/6/90

TYPE OR PRINT NAME J.D. Rawdon

TELEPHONE NO. 405-789-5053

(This space for State Use)

APPROVED BY Jerry Spitz TITLE General Manager DATE NOV 13 1990

CONDITIONS OF APPROVAL, IF ANY:

Will have to use tubing to set casing