110908 (119105 1100

120 MY (4 M 3: 44

In order to return well to production it is proposed to squeeze cement, perforate and acid treat as follows:

1. Pull 2-3/8" tubing and packer.

2. Run 2-3/8" tubing with 4-3/4" bit and drill out Hydromite from 3800-3844'. Pull tubing and bit.

3. Run 2-3/8" tubing and 5-1/2" cement retainer set at 3765'. Squeeze cement interval below retainer. Pull 2-3/8" tubing. WCC. Run 2-3/8" tubing with 4-3/4" bit and drill out cement to 3826'. Pull tubing and bit.

4. Perforate 5-1/2" casing from 3800-3824' with 4, 1/2" jet holes per foot. Run 2-3/8" tubing with Hookwall packer. Treat perforations in 5-1/2" casing with 2000 gallons 15% NE scid. Swab and test.

5. If commercial production is not gained, pull tubing and packer. Perforate 5-1/2" easing from 3760-3772' and 3778-3795'.

6. Run 2-3/8" tabing with bridge plug set at 3796' and parent packer set at 3750'. Freat formation with 4000 gallons 15% ME acid. Swab and test.

7. Pull 2-3/8" tubing, bridge plug and parent packer. Rerun 2-3/8" tubing and return well to production.

ನಿವರ್ಷದ ಕರ್ನ್ನವಾಗ ಇವರ ಸಂಗೀತವಾಗ ಸಹಗಳ ಸಂಗ್ರಹಗಳು, ಇದ್ದಾರು ಕರ್ನಿಷ್ಟಿಯ ಕ್ಷಮಿಕ ವಿಧಾರ್ಯಕ್ಷವೆ ಗೆರು<mark>ಬ್</mark>ಳಾಗಿತ್ತು. ಕರ್ನಿಕ ಮತ್ತು ಮುಂದು ಕ್ಷಮಿಗಳು ಮುಂದು ಕ್ಷಮಿಗಳು ಪ್ರತಿಕ್ರಿಸಿದ ಕ್ಷಮಿಗಳು ಪ್ರತಿಕ್ರಿಸಿದ ಕ್ಷಮಿಗಳು ಕ್ಷಮಿಗಳು ಪ್ರತಿಕ್ರಿಸಿದ ಕ

•

Commission of the second of the second

The first of the first of the second of the second of the first of the first of the second of the se المسلف فالمقتل بيانيات المؤثيين

and the second of the second o

Little Country of Fig. 19 and 18th of 12