

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- 2. Name of Operator Chevron U.S.A. Inc. 3. Address of Operator P.O. Box 670, Hobbs, NM 88240 4. Location of well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>20S</u> RANGE <u>36E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3554	7. Unit Agreement Name Eunice Monument S. 8. Farm or Lease Name Unit 9. Well No. 139 10. Field and Pool, or Wildcat Eunice Monument G/S 12. County Lea
--	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER <u>dpn, log, acdz</u>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed 5-29 thru 6-11-88 TD: 4008

POOH w/ production equipment. Break circulation w/air mist. Drlg form f/3825 to 4004. Ran CNL, CCL, GR, caliper. RIH w/ 5 1/2", 24#, liner set at 4008', TOL at 3440'. Cmt w/100sx C1 C. Disp. w/FW, WOC 24 hrs. Drill out cmt, run GR/CCL/CBL. Perf 3860-70, 3848-52, zone 4 & 5. w/1 JHPF 0°phase, spot 100 gal 15% NEFE across perf interval 3948-3970. Acdz zone 4 & 5 w/700 gallons 15% NEFE, swab. RIH w/4" perf guns, perf zones 2 & 3 at 3880-3902, 385-3870, 3828-3846, 3804-3820, w/ 1 SPF, 0° phase, Acdz perf interval zones 2 & 3 w/3400 gal NEFE. Swab. Est. circ. w/air mist. DO cmt to 4006, circ. hole clean. Perf w/4" perf gun, zone 5 w 1SPF. 0 phased 3988 - 3992'. 4 shots fired. Spot 100 gallons NEFE across interval Acdz perf interval, zone 5 3988-3992, w/250 gallons NEFE, Swab. RIH w/CIBP set same inside 5 1/2" liner at 3798'. Test to 500psi, ok. RIH w/4" gun, perf zone 1, 3780-90 and 3764-69, 15 holes total. Spot 100 gallons 15% NEFE HCL across perfs 3764-3790. Put spot away, pump 700 gallons NEFE and swab. RIH w/ 2 7/8" 6.5#, J-55 prod. tbg to 3986, SN at 3949'. TAC 3636. Run rods and pump. Space out and hang off. Test pump to 500psi, ok. Turn over to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. E. Sexton TITLE Drlg. Tech. Asst. DATE July 1, 1988

ORIGINAL SIGNED BY LARRY SEXTON

APPROVED BY DISTRICT MANAGER TITLE DATE
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 8 1988

ODD
HOBBS OFFICE

RECEIVED

JUL 6 1988

ODD
HOBBS OFFICE