

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-78

NO. OF EXPLORATION	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

OG-4067-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)OIL WELL ☐ GAS WELL ☒ OTHER ☐

7. Unit Agreement Name

8. Farm or Lease Name

New Mexico "CV" State

9. Well No.

1

10. Field and Pool, or Vldcat

Ole. to Morrow

UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 36 TOWNSHIP 20S RANGE 35E B.M.P.M.15. Elevation (Show whether DF, RT, GR, etc.)
3661 DF12. County
LeaCheck Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:PERFORM REMEDIAL WORK ☒TEMPORARILY ABANDON ☐PULL OR ALTER CASING ☐OTHER ☐PLUG AND ABANDON ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPS. ☐CASING TEST AND CEMENT JOB ☐OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRUPU. Kill well w/2% KCL water. Install BOP. Baker Model FA is a permanent pkr & will have to be milled. Release prod. pkr set @ 11,325'. Records indicate Baker Model FA pkr @ 11,325'. Keep hole full.
- 2) TOH w/2 3/8" prod. tbg. and seal assembly (packer). A Baker Model "K" straddle packoff was installed in 1977, top @ 11,301', bottom @ 11,310', and is probably still set in the 2 3/8" tbg. (csg. perfs @ 11,378-422', tbg peft. @ 11,305').
- 3) TIH w/cmt. retainer and set @ + 11,250'. Sting into retainer and cement squeeze perfs @ 11,378-422' (20holes) w/100 sxs class "H" cement w/1% Halad-9. WOC.
- 4) TIH w/3 3/4" bit on workstring. Lower bit to cmt. retainer and drill out. Burn over Model FA PKR @ 11,325. Drill out cmt. to PBTD 11,554'. Drill out 4 1/2" csg. from 11,554' to 11,600. Circulate until clean.
- 5) Close pipe rams in BOP. Pressure test 4 1/2" csg. to surface @ 2500# for 30 minutes. If any leaks are found, TOH w/bit. TIH w/pkr and locate leaks. Cement squeeze leaks as necessary. WOC, drill out, and test.
- 6) TIH w/prod. pkr. Lower pkr. to 11,580', then spot 250 gal 7 1/2% acetic acid @ 11,200-11,580'. Raise pkr. and set @ 11,150'. Swab fluid level down to 8500'. ND BOP's NU Tree & Test to 2500 PSIG.
- 7) Perf. the Morrow w/ 9/16" tbg. gun, 1 spf, @ 11,235, 44, 50, 52, 56, 59, 62, 65, 69, 80, 85, 11,306, 16, 20, 11,474, 99, 11,518, 24, 27, 30, 33, 36, 39, 41, 44, 53, 56, 59, 61, 64, 66, 70 and 11,572' (total 34 holes). **SEE BACK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. B. Sexton
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISORTITLE District Oper. ManagerDATE 01/27/86

PROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL _____

FEB 3 - 1986

Swab well and attempt to flow, then test. If well will not flow sufficiently, prepare to acidize perfs.

Load annulus w/2% KCL water. Treat all Morrow perfs @ 11,235-572' (34 holes) w/4,000 gal. 15% NEFE w/clay stabilizers. Drop 50 ball sealers throughout job, pumped @ 3 BPM, 3500#, utilizing 6 gal. friction reducers. Flush to pkr. w/2% KCL water. SI 45 minutes, then swab well and attempt to flow. Test and evaluate flowrate.

If rate is sufficient, remove BOP & NU Tree and RDP.

If rate is not sufficient, evaluate for possible additional stimulation.

Should the Morrow not be productive, prepare to cement squeeze perfs and recompleat to the Atoka

Kill well. ND Tree. NU BOP's. Keep hole Full. Release pkr. and TOH.

TIH w/4 1/2" cmt. retainer and set @ 11,220'. Set into retainer and pump 100 sxs class "H" cmt. w/1% Halad-9. Pull out of retainer and reverse circulate the tbgs. until clean. TOH w/workstring WOC & test csg to surface at 1.25 times. Anticipated SI Atoka pressure. NB.

TIH with pkr and workstring. Spot 300 gal. 7% acetic acid across the interval 10,770-11,210'. Raise pkr. and set @ 10,700'. ND BOPs. NU Tree & test to atoka press. Swab FL down to 8000'. Perforate the Atoka w/1 9/16" tbgs. gun, 1 spf, @ 10,770, 73, 76, 81, 94, 98, 10,800, 03, 06, 11, 16, 20, 25, 50, 10,984, 87, 90, 94, 11,015, 17, 28, 30, 33, 36, 38, 43, 48, 51, 54, 70, 74, 77, 110,104, 11, 14, 20, 23, 26, 30, 33, 36, 42, 45, 48, 50, 62, 66, 72, 75, 81, 84, 93, 96, 99, 11,203 and 11,206' (total 56 holes).

Swab well and attempt to flow. Test flowrate. If well will not flow sufficiently, prepare to acidize perfs.

Treat entire Atoka interval 10,770-11,200 with 6000 gals 15% NEFE acid and clay stabilizers. Drop 100 ball sealers throughout job, pumped @ 5 BPM, 4500# utilizing 5 gal friction reducer. SI well 1 hour then swab and attempt to flow. Test and evaluate production.

RECEIVED

FEB - 3 1986

O.C.D.
HOBBS OFFICE