STATE OF NE ENERGY AND MINERA			محافر		
DISTRIBUTION DIL CONS		P. O. BO)	SERVATION DIVISI N P. O. BOX 2088 E, NEW MEXICO 87501		Form C-103 Revised 10-1-78
FILE U.S.G.S.				ſ	5a. Indicato Type of Lease State XX Foe
LAND OFFICE			·	-	State XX Fee 5. State Oil & Gas Lease No.
OPERATOR					E-5230-1
(DO NOT USE TH	SUNDRY NOTICES AND USE "APPLICATION FOR PERMIT - " (	D REPORTS ON TO DEEPEN OF PLUG & FORM C-101) FOR SUC	WELLS ACK TO A DIFFERENT RESERVOIR + PROPOSALS.)		7. Unit Agreement Name
OIL X	GAS OTHER-	•			
2. Name of Operator					8. Form or Lease Name
JFG Ent 3. Address of Operator	erprise				Little Eddy Unit 9. Well No.
P.O. Box 100, Artesia, NM 88211-0100					16- <del>1</del> 10. Field and Pool, or Wildcat
4. Location of Well	F 2310 FEET FRO	North	2310		Halfway-Yates
	LINE, SECTION 16			L L	
mmm	[[[]]] 15. Elev	ation (Show whether	DF, RT, GR, etc.)		12. County
		<u>3510 DF</u>			Lea Allalli
16. N	Check Appropriate Bos OTICE OF INTENTION TO:	x To Indicate N	-		er Data REPORT OF:
PERFORM REMEDIAL WOR	1K 🚺 PLL	JG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPHS.		PLUG AND ABANDONMENT X
PULL OR ALTER CASING	СНА	ANGE PLANS	CASING TEST AND CEMENT JOB Other		
OTHER					
17. Describe Proposed	or Completed Operations (Clearly st	ate all pertinent deta	ils, and give pertinent dates,	including e	stimated date of starting any proposed
work) SEE RULE 2-11-87	Rig up Pulling Unit, lay down rods and pump. Pull 2 7/8" tubing. Pick up and run 2 3/8" Tubing. Tag up at 2590 ft. Pull 1 joint. End of tubing 2560'. Shut down - Will spot tubing next A.M. NOTE: End of 4 <sup>1</sup> 2" Casing at 2587 ft., original TD 2591 ft.				
2-12-87	Rid up Denton Cement Co. Spot 20 sk. plug at 2560 ft. w/4% Cal. Clr. Class "C" Cement - wait 2½ hrs. Tag up at 2130 ft. 430 ft. fill. Mix 50 sks. Cl "C". Spot at 2130 ft. Pull 730 ft. Mix & pump 50 sk. pluz @ 1400 ft. Casing went on vacuum - Pull out of hole. Shut down, will tag next A.M.				
2-13-87	Run Wire Line-Tag cement 2024 ft. Fluid level 1400 ft. from surface. Mix 20 sks. Class "C" w/4% Cal. Cl. at 1610 ft. Pull up. After 2 hrs. tag with wire line @ 1992 ft. 32 ft. fill. Run tubing to 1610 ft. Mix 20 sks. Cl "C" w/4%. Tag w/wire line 1785 ft. Mix & pump 50 sks. Cl "C" w/2% Cal. Clr. Pull 23 jts. Shut down - 29 jts. in hole = 906 jts.				
2-16-87	Ran Wire Line - Tag up 1785 ft. No fill - Mix & pump 20 sk. Cl "C" w/2% Cal. Clr. Tag $2\frac{1}{2}$ hrs. 1636 ft. 149 ft. fill Mix 20 sks.2% Cal. Clr. Tag 2 hrs. 1536' - 100 ft. fill. Mix & pump 30 sks. Cl "C" w/2% = 2 hrs. 1230 ft.= 306 ft. fill. Mix 30 sks. Tag up 1490 ft. Mix 20 sks. 2% Cal. Clr. Pull Tubing. Shut down (OVER)				
18. I hereby certify the	t the information above is true and c	complete to the best of	f my knowledge and belief.		
\$ 1GNED		TITLE	Agent		DATE <u>3-25-87</u>
P.M.	Talle	OIL 3	GAS INSPECT	OR	JAN - 4 1988
CONDITIONS OF APP	ROVAL, IF ANY:				

- 2-17-87 Tag Up w/wire line 1560 ft. Lost 70 ft. Run tubing to 1600 ft. Mix & pump 20 sks. Cl "C" w/2% Cal. Clr. Tag up at 1377 ft. 183 ft. fill. Let set 2 hrs. 45 min. Mix & pump 30 sks. Cl "C" w/2%. Shut down.
- 2-18-87 Tag up 988 ft. Mix & pump 40 sks. Cl "C" w/2%. Tag up 500 ft. Mix 40 more sks. Cl "C" w/2% Cal Clr. Casing full cement, used total 460 sks. Install Dry Hole Marker, rig down.
  - NOTE: Plugging operations witnessed by New Mexico Oil Commission representative Jack Griffin.



.