

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1731

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name New Mexico 'CU' State Gas Comm
3. Address of Operator P.O. Box 728 - Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM West LINE, SECTION 31 TOWNSHIP 20-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Osudo Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3658' (DF)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set a CIBP in the Otis "WA" packer at 10,990' and cap with 30' (3 sx) of cement.
- Load hole with 10# mud.
- Cut and pull 4-1/2" casing at freepoint (approx. 8000').
- Spot a 100' (21 sx) cement plug across 4-1/2" casing stub.
- Spot a 100' (34 sx) cement plug adjacent to 8-5/8" casing shoe.
- Cut and pull 8-5/8" casing at freepoint (approx. 3500').
- Spot a 100' (49 sx) cement plug across 8-5/8" casing stub.
- Spot a 100' (65 sx) cement plug adjacent to the 11-3/4" casing shoe.
- Spot a 10' (7 sx) cement plug at surface.
- Install marker and clean location.

100' PLUG 10' OF 8-5/8" CIBP
100' PLUG 10' OF 8-5/8" CIBP
100' PLUG 10' OF 8-5/8" CIBP

THE ABOVE WELL WAS DRILLED 24
AT 10:00 AM ON 6-13-79
BY JERRY SEXTON, DIST. 1, SUPV.
TO BE PLUGGED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst. Dist. Supt. DATE 6-13-79

APPROVED BY Jerry Sexton TITLE Dist. 1, Supv. DATE JUL 9 1979

CONDITIONS OF APPROVAL, IF ANY: