N I. OF COPIES RECEIVED	]		Form C-103	
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION		Supersedes Old C-102 and C-103	
SANTA FE			Effective 1-1-65	
FILE				
U.S.G.S.			Sa. Indicate Type o	f Lease
LAND OFFICE			State	Fee X
OPERATOR	J		5, State Oil & Gas	Lease No.
			-	
SUNDRY NOTICES AND REPORTS ON WELLS  [DO NOT USE THIS FORM FOR PROPORALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "PAPPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)				
OIL X GAS WELL	OTHER-		7. Unit Agreement N	Name
Among Dynadysetian Communication			8. Farm or Lease N	ame
Amoco Production Company			South Hobbs	(GSA) Unit
. Address of Operator	land Taura 70226		9. Well No.	
P.O. Drawer A Level	86			
i, Location of Well			10. Field and Pool, or Wildcat	
UNIT LETTER K 2310 FEET FROM THE SOUTH LINE AND 1650 FEET FROM			Hobbs- GSA	
		77/////////////////////////////////////		
THE West LINE, SECTION 10 TOWNSHIP 19-S RANGE 38-E NMPM.				
, , , , , , , , , , , , , , , , , , ,			VIIIIIII.	
	15. Elevation (Show whether	Dr, KI, GK, etc.)	12. County	
	3598 GR	·	Lea	7777777777
	Appropriate Box To Indicate N			
NOTICE OF IN	NTENTION TO:	SUBSEQUEN	T REPORT OF:	
PERFORM REMEDIAL WORK				
Ħ	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	=
PULL OR ALTER CASING		COMMENCE DRILLING OPNS.	PLUG AND	ABANDONMENT
POLE OR RETER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		
OTHER		OTHER	<del></del>	L
	perations (Clearly state all pertinent deta			
tubing, drill collar, Pull tubing, drill collar, Pull tubing, drill co casing. Test casing 10 BFW. Cemented 8-5 10 sx. WOC 24 hrs. Ran tubing and packer 150# mothballs, and 3 packer and tubing. So 1000 gal. 20% WE acid water. Unseated brid Acidize zone I in two and 300 gal. gel water packer 4010'. Pulled	9-14-78. Pull rods, pumsing cutter, drill collacutter, and 5½" casing. Plar, and bit. Ran 6-3/500# for 15 min. Test o/8" surface casing with Perforated 4024'-50', 40. Set packer at 4187'. 00 gal. gelled water. Pet bridge plug at 4187' in two stages with 150# ge plug and packer. Set stages with 1000 gal. 20 r. Unseated bridge plug bridge plug and tubing. Well on production. Production.	Run dress off tool to Run dress off tool to Y4" Bowen casing bowl to bk. Hooked up Howco to be 50 sx CACL INCOR.plus and Acidize zone III with Yull packer and tubing, and set packer at 4138', mothballs between stage bridge plug at 4138' ar 0% NE acid separated by and packer. Set bridge Ran 2-7/8" tubing rook.	Cut 5½" 14# catop of 5½" ca680'. Bowl obraden head. dditives. Cir4200'-10' wi1000 gal. 20% Ran ret. bride. Acidize zones, and 300 gand set packer 150# graded me plug at 4097	asing. Pulasing (680') byer 5½" Pumped rculated ith 2 JSPF. NE acid dge plug, ne II with al. gelled at 4097'. nothballs '' and set
14. I hereby certify that the information  GIGNED Change Crang  Orig.  John		of my knowledge and belief. st. Admn. Analyst		20-78 25 <b>1</b> 978
APPROVED BY	doglet TITLE		. DATE CO	
CONDITIONS OF APPROVAL, IF ANY:				

0+4 - NMOCC-H 1 - SUSP 1 - REG 1 - DE