DESTRUCTION NEW MEXICO OIL COMSERVATION COMMISSION Some of the state	NO. OF COPIES RECEIVED	 기	
Support NEW MEXICO OIL CONSERVATION COMMISSION Support Compared Completed Completed Completed Completed Completed Completed Compared Completed Completed Compared Completed		-	Form C - 102
Subsection Sub			Supersedes Old
Support Supp		NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
Sunders Top of Lease State Fee S. State Fee Fee S. State Fee		1	
Substitute of the proposed of Completed Operations (Clearly anter all puriness desired and pu		-	5a. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS OF WELLS OUT OF THE PROPERTY OF TH		-	
SUNDRY NOTICES AND REPORTS ON WELLS ON THE THIS POSSESSED AND ACCOUNTS ON THE STATE OF THE STAT	J. Z.I.X.I OK	,	
Springs MCF 011 Corporation 1. Address of Operation 1. Address of Op	Cluster		
Springs MCF 011 Corporation 1. Address of Operation 1. Address of Op	(DO NOT USE THIS FORM FOR PRO	LY NOTICES AND REPORTS ON WELLS	
NEL WELL STATES		(FORM C-101) FOR SUCH PROPOSALS.)	
Springs Springs Sprin	WELL WELL	OTHER- Wildcat - attempt completion in Bone	7. Unit Agreement Name
Perla 1.26 Vaughin Building, Midland, Texas 79701 1. Location of No. 1. Location of	•	Springs	
1126 Vaughn Building, Midland, Texas 79701 4. Location of Well WITH LETTER J . 2310 THE TROW THE SOUTH 1980 TOWNSHIP 198 AALES 36E WILLIAM SOUTH 1980 TOWNSHIP 198 AALES 36E TOWNSHIP 198 TOWNSHIP 198 AALES 36E TOWNSHIP 198 TOWNSHIP 198 AALES 36E WILLIAM SOUTH 198 TOWNSHIP 198 TOWNSHIP 198 TOWNSHIP 198 TOWNSHIP 198 TOWNSHIP 198 AALES 36E WILLIAM SOUTH 198 TOWNSHIP 198 AALES AALES AALES ARE STUREN SOUTH 198 TOWNSHIP 198 AALES AALES AALES CASING TOWNSHIP 198 TOWNSHIP 198 AALES AALES AALES CASING FILLS AALES AALES CASING TOWNSHIP 198 AALES AALES AALES CASING FILLS AALES AALES CASING TOWNSHIP 198 AALES AALES AALES CASING FILLS AALES CASING TOWNSHIP 198 AALES AALES AALES CASING FILLS AALES AALES CASING FILLS AALES CASING TOWNSHIP 198 AALES AALES AALES CASING FILLS AALES CASING TOWNSHIP 198 AALES AALES CASING FILLS AALES CASING TOWNSHIP 198 AALES AALES CASING FILLS AALES CASING TOWNSHIP 198 AALES AALES CASING FILLS AALES CASING FILLS AALES CASING FILLS AALES CASING AALES AALES CASING FILLS AALES CASING AALES AALES CASING FILLS AALES CASING AALES AALES CASING FILLS AALES CASING AALES AALES CASING	MGF Oil Corporation	·	i
Lecolino I Well Line Secrition 19 Line East Line Secrition 19 Local South Line and 1980 Local South Line and 1980 Line South Line and 1980 Local Line Secrition Wilden Wilded Wildcat Wildcat Wildcat Wildcat Wildcat Wildcat Local South Line and 1980 Local Line Secrition Wilden Wildcat Wi			
UNIT LETTER J . 2310 FEET FROM THE SOUTH THE EAST LINE, SECTION 19 TOWNSHIP 198 AASE 36E Wildcat 15. Elevation (Show inhether DF, RT, GR, etc.) 3691 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: PLUE AND ABANDON THAT DATE CASING THAT DATE CASING THAT DATE CASING THAT DATE CASING Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 1,980'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Top 7 5/8 liner - 5046'. Top salt 1963'. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.	1126 Vaughn Building, Midland, Texas 79701		
THE East LINE, SECTION 19 TOWNSHIP 198 AND 36E NAME OF THE POOR THE SOUTH 198 AND SOUT			
THE East LINE, SECTION 19 TOWNSHIP 198 RANGE 36E NAME 12, County 12, County 12, County 14, County 15, Elevation (Show whether DF, RT, GR, etc.) 12, County 12, County 16. 12, County 16. 12, County 16. 16. 17, Control 16. 17, Control 16. 17, Control 17, Contro	UNIT LETTER J 2	2310 FEET FROM THE South 1980	*****
The Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Notice of Intention to:			FROM WIIGCE
The Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Notice of Intention to:	THE LAST LINE, SECTIO	N1919S36E	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK TEMPORABILY ABANDON TEMPORABILY ABANDON TEMPORABILY ABANDON THEM 17. Describe Proposed on Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or complete Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Pull up to 1,980'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.	mmmmmm		MMPM. (111111111111111111111111111111111111
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of			12 County
Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Top 7 5/8 liner - 5046'. Top 3 St. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.	16.		
Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Top 7 5/8 liner - 5046'. Top 3 St. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.	Check A	ppropriate Box To Indicate Nature of Notice D	
PLUE AND ABANDON SEMEDIAL WORK CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMERCE DRILLING OFFIS. CASING TEST AND CEMENT JOB CHANGE PLANS CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB CASING TE	NOTICE OF IN	TENTION TO:	r Other Data
PLUG AND ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103. Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Pull up to 1,980'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Top 7 5/8 liner - 5046'. Top salt 1963'. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.		SUBSEQU	JENT REPORT OF:
OTHER OTHER OTHER Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Top 7 5/8 liner - 5046'. Top 35/8 liner - 5046'. Top 35/8 liner - 5046'. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.		PLUG AND ABANDON	י
Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Pull up to 1,980'. Spot 50 Sx. plug 136'. Top 7 5/8 liner - 5046'. Top salt 1963'. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.	TEMPORARILY ABANDON	The state of the s	ALTERING CASING
Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Pull up to 1,980'. Spot 50 Sx. plug 136'. Top 7 5/8 liner - 5046'. Top salt 1963'. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.	PULL OR ALTER CASING		PLUG AND ABANDONMENT
Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Top 7 5/8 liner - 5046'. Top salt 1963'. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.		SOUTH TEST AND CEMENT JOB	
Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Pull up to 1,980'. Spot 50 Sx. plug 136'. Top 7 5/8 liner - 5046'. Top salt 1963'. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.	OTHER	OTHER	
Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Pull up to 1,980'. Spot 50 Sx. plug 136'. Top 7 5/8 liner - 5046'. Top salt 1963'. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.	17. Describe Proposed G		
Drill out existing plugs and clean out to 10,450'. Set Howco CIBP @10,450' with 20' cement. Perforate Bone Springs 9985-9994. Run tubing and packer. Test Non Commercial. Pull tubing and packer. Go back in hole to 10,420'. Spot 10 Sx. cement, 46'. Displace hole with 9.2 salt water w/25 Sx. salt jell per 100 Bbl. Spot 70 Sx. plug 9,880'. Shut down overnight. Tag plug 185' in pipe. Pull up to 5,107'. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9 5/8. Pull up to 1,980'. Spot 50 Sx. plug 136'. Top 7 5/8 liner - 5046'. Top salt 1963'. Put 10 Sx. plug @ surface and install dry hole marker and cut off anchors. See copy of Clayton W. Williams Form C-105, submitted 9-15-74.	work) SEE RULE 1903.	rations (Clearly state all pertinent details, and give pertinent dates, incli-	uding estimated days of
GRED Gaula Engineer 11-11-74	Commercial. Pull cement, 46'. Dis Spot 70 Sx. plug Pull up to 5,107' Pull up to 1,980' Top 7 5/8 liner - Top salt 1963'. Put 10 Sx. plug @	tubing and packer. Go back in hole to 10, splace hole with 9.2 salt water w/25 Sx. sale 9,880'. Shut down overnight. Tag plug 185. Spot 50 Sx. plug 69' in 7 5/8, 110' in 9. Spot 50 Sx. plug 136'. 5046'.	nd packer. Test Non 420'. Spot 10 Sx. t jell per 100 Bbl. ' in pipe. 5/8.
German Engineer 11-11-74			
TITLE Engineer 11-11-74	. I hereby certify that the information abo	we is true and complete to the best of my Know halon and true	
C. C. Complete		of the straight and netter,	
C. C. Carod La	ENED Saula	Fraince	
O. C. Canad Kin	- /	TITLE PURTIFEE	11-11-74
PROVED BY FOLLOWS AND THE STATE OF THE	Q. C. Come	Ka	
	PROVED BY	∪y _i	FEB 21 8/5

RECEIVED

NOV 1 4 1974

UIL CONSERVATO 1 2000A. HOBBS, N. II.