

Dec. 1973

P. O. BOX 1940

UNITED STATES

HOODS, NEW MEXICO 88304

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Form Approved.

Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR

Superior Oil Company, The

3. ADDRESS OF OPERATOR

P.O. Box 3901, Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

1980' FNL, 1980' FEL

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON* ☒(other) ☐

5. LEASE

NM-13644A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Featherstone Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Featherstone

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 21, T20S, R35E

12. COUNTY OR PARISH 13. STATE

Lea

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3716' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Procedure for P&A Operations

1. Notify BLM
2. Load hole w/gelled 9.5# brine.
3. Set 7-5/8" CIBP @ 5250', test to 1000 psi, dump bail 50' cmt on top of CIBP.
4. Determine free point of 7-5/8" csg, (TOC at approx. 4800').
5. Cut 7-5/8" csg at free point & POH.
6. Spot 100' (53 sx @ 50% excess) Class C Neat cmt plug on top of 7-5/8" csg (50' inside csg, 50' inside open hole, displace cmt w/gelled 9.5# brine, tag TOC.
7. Spot 100' (75 sx @ 50% excess) Class C Neat cmt plug @ 10-3/4" csg shoe (4421') from 4371-4471' (50' inside csg, 50' in open hole). Displace w/gelled 9-5# brine, WOC, tag TOC.

Subsurface Safety Valve: Manu. and Type

Set @

(Over) Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

G. F. Tate

TITLE Division Opr. Supt. DATE 11-12-84

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1976 O - 214-140

NOV 17 1984

8. Spot 50' (31 sx @ 50' excess) Class C Neat cmt plug @ surface.
9. Cut csg 3' below ground level, weld on steel plate w/4' marker.
10. Level cellar and location.