Submit 3 Copies to Appropriate District Office	State of New Me Energy, Minerals and Natural	Form C-103 Revised 1-1-89		
DISTRICT I P.O. Box 1980, Hobbs NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088			WELL API NO.	<u> </u>
DISTRICT II 811 S. 1st Street, Artesia, NM 88210-2834 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			5. Indicate Type of Lease	
			STATE 6. State Oil & Gas Lease No.	FEE C
SUNDRY NOTICES AND REPORTS ON WELLS			<u>NM-02127-В</u>	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name LEA UNIT	
1. Type of Well: OIL WELL GAS WELL] OTHER SWD W	ELL		
2. Name of Operator Marathon 011 Company			8. Well No. 2	
3. Address of Operator P.O. Box 2409, Hobbs, NM 88240			9. Pool name or Wildcat LEA	
4. Well Location Unit Letter L : 162	25 Feet From The SOUTH	Line and 33	BO Feet From The	WEST Line
Section 12	10. Elevation (Show wheth		<u>NMPM</u> :.)	LEA County
11. Check A	ppropriate Box to Indicate		Report, or Other Dat	//////////////////////////////////////
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
		REMEDIAL WORK		
		COMMENCE DRILLING		
OTHER: 12. Describe Proposed or Completed Ope				
<pre>work) SEE RULE 1103. Class C cmt. Bumped plug. Float held ok. Pumped 63sx Class C cmt down annulus. RD Halliburton. NU spool and BOP. RIH w/4-3/4" bit. Tagged float collar @ 3654'. Tested to 1000#. Held ok. POOH. RU wedge Dialog. RIH w/CBL tool. Tagged cmt @ 3698'. Ran CBL from 3698' to surface. RD Wedge wireline. NOTE: Verbal approval given by OCD to drill out CIBP after looking at CBL. RIH w/4-3/4" bit. Tagged cmt on plug @ 3703'. Drilled cmt, plug and cleaned out to 4569'. POOH. RIH and set Baker pkr @ 3569'. RU Halliburton. Acidized San Andres Open Hole interval 3800'.4600' w/10000 gals 15% Ferchek SC acid. RD Halliburton. Released pkr. POOH. RU testers. RIH hydrotesting w/5-1/2" packer, on-off tool on 3-1/2" J55 IPC tubing. Set pkr @ 3680'. Release tubing from on-off tool. Circulate well w/2% KCL water & packer fluid. Latch onto on-off tool. ND BOP. NU wellhead. Pressure up backside to 500 Psi. Held ok for 30 minutes. Pressured up tubing to 1500 Psi. Sheared pump-thru plug. RDPU.</pre>				
land he	true and complete to the best of my knowledg			0.19.1006
V		TLE		9-18-1996
TYPE OR PRINT NAME Ralph Skinne (This space for State Use)			TELEPHONE NO.	505-393-7106
APPROVED BY	τπι	Æ	DATE	

